

HISTORIC AND DESIGN REVIEW COMMISSION

October 18, 2023

HDRC CASE NO:	2023-400
ADDRESS:	927 N OLIVE ST
LEGAL DESCRIPTION:	NCB 530 BLK 14 LOT E158. 33FT OF S 50FT OF A3 ARB A17 AT 927 N OLIVE
ZONING:	R-5, H
CITY COUNCIL DIST.:	2
DISTRICT:	Dignowity Hill Historic District
APPLICANT:	arturo lopez/A.L.E trucking
OWNER:	arturo lopez/A.L.E trucking
TYPE OF WORK:	Porch column modification
APPLICATION RECEIVED:	September 21, 2023
60-DAY REVIEW:	November 20, 2023
CASE MANAGER:	Claudia Espinosa

REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to clad the existing wooden columns, capitals, and base with 1x8 softwood boards.

APPLICABLE CITATIONS:

Historic Design Guidelines, Chapter 2, Exterior Maintenance and Alterations

1. Materials: Woodwork

A. MAINTENANCE (PRESERVATION)

- i. *Inspections*—Conduct semi-annual inspections of all exterior wood elements to verify condition and determine maintenance needs.
- ii. *Cleaning*—Clean exterior surfaces annually with mild household cleaners and water. Avoid using high pressure power washing and any abrasive cleaning or striping methods that can damage the historic wood siding and detailing.
- iii. *Paint preparation*—Remove peeling, flaking, or failing paint surfaces from historic woodwork using the gentlest means possible to protect the integrity of the historic wood surface. Acceptable methods for paint removal include scraping and sanding, thermal removal, and when necessary, mild chemical strippers. Sand blasting and water blasting should never be used to remove paint from any surface. Sand only to the next sound level of paint, not all the way to the wood, and address any moisture and deterioration issues before repainting.
- iv. *Repainting*—Paint once the surface is clean and dry using a paint type that will adhere to the surface properly. See *General Paint Type Recommendations* in Preservation Brief #10 listed under Additional Resources for more information.
- v. *Repair*—Repair deteriorated areas or refasten loose elements with an exterior wood filler, epoxy, or glue.

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

- i. *Façade materials*—Avoid removing materials that are in good condition or that can be repaired in place. Consider exposing original wood siding if it is currently covered with vinyl or aluminum siding, stucco, or other materials that have not achieved historic significance.
- ii. *Materials*—Use in-kind materials when possible or materials similar in size, scale, and character when exterior woodwork is beyond repair. Ensure replacement siding is installed to match the original pattern, including exposures. Do not introduce modern materials that can accelerate and hide deterioration of historic materials. Hardiboard and other cementitious materials are not recommended.
- iii. *Replacement elements*—Replace wood elements in-kind as a replacement for existing wood siding, matching in profile, dimensions, material, and finish, when beyond repair.

7. Architectural Features: Porches, Balconies, and Porte-Cocheres

A. MAINTENANCE (PRESERVATION)

- i. *Existing porches, balconies, and porte-cocheres*—Preserve porches, balconies, and porte-cocheres. Do not add new porches, balconies, or porte-cocheres where not historically present.
- ii. *Balusters*—Preserve existing balusters. When replacement is necessary, replace in-kind when possible or with balusters that match the originals in terms of materials, spacing, profile, dimension, finish, and height of the railing.
- iii. *Floors*—Preserve original wood or concrete porch floors. Do not cover original porch floors of wood or concrete with carpet, tile, or other materials unless they were used historically.

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

- i. *Front porches*—Refrain from enclosing front porches. Approved screen panels should be simple in design as to not change the character of the structure or the historic fabric.
- ii. *Side and rear porches*—Refrain from enclosing side and rear porches, particularly when connected to the main porch or balcony. Original architectural details should not be obscured by any screening or enclosure materials. Alterations to side and rear porches should result in a space that functions, and is visually interpreted as, a porch.
- iii. *Replacement*—Replace in-kind porches, balconies, porte-cocheres, and related elements, such as ceilings, floors, and columns, when such features are deteriorated beyond repair. When in-kind replacement is not feasible, the design should be compatible in scale, massing, and detail while materials should match in color, texture, dimensions, and finish.
- iv. *Adding elements*—Design replacement elements, such as stairs, to be simple so as to not distract from the historic character of the building. Do not add new elements and details that create a false historic appearance.
- v. *Reconstruction*—Reconstruct porches, balconies, and porte-cocheres based on accurate evidence of the original, such as photographs. If no such evidence exists, the design should be based on the architectural style of the building and historic patterns.


FINDINGS:

- a. The primary structure located at 927 N Olive, previously addressed as 917 N Olive, is a 1-story single-family structure constructed circa 1930 in the vernacular style and makes its first appearance in the 1931 Sanborn Map. The address change from 917 to 927 N Olive was noted on the 1951 Sanborn Map. The home features a full-length porch, a mix of lap siding and asbestos siding, one-over-one windows, and non-original 4x4 porch posts. The home is contributing to the Dignowity Hill Historic District.
- b. PORCH MODIFICATIONS – The applicant has proposed to wrap the existing columns with 1x8 softwood boards (photos submitted indicate a very thin veneer being added.) According to the Historic Design Guidelines, porches should be reconstructed based on accurate evidence of the original, such as photographs. If no such evidence exists, the design should be based on the architectural style of the building and historic patterns. The proposed column modification is appropriate in terms of materials, but do not conform to the Guidelines which require a traditional column base and cap as well as chamfered corners.

RECOMMENDATION:

Staff does not recommend approval of the porch column modifications based on finding b. Staff recommends that the applicant install a replacement column that meets the Guidelines with the following stipulations: The proposed wood columns should be no wider than 6" square, feature both capital and base trim and chamfered corners.

City of San Antonio One Stop



October 13, 2023

1:1,000
0 0.0075 0.015 0.03 mi
0 0.0125 0.025 0.05 km





927

927

REHAB
IN PROGESS













10:54

17


Home / Paint / Exterior Wood Coatings / Exterior WO



Olympic

Maximum 1 gal. Canyon Brown Exterior Stain and Sealant in One

★★★★★ (2501) ▾



TRANSPARENT

MAXIMUM.

OLYMPIC®



\$41.98
/gallon

-

1

+

Add to Cart

10:53

17

● OPEN until 10 pm

Home / Lumber & Composites / Boards, Planks & Pan

Top Rated



1 in. x 8 in. x 8 ft. Premium Kiln-Dried Square Edge Common Softwood Boards

★★★★★ (372) ▾



BULK ⚡ 1 - 70

- 1 +

Add to Cart