HISTORIC AND DESIGN REVIEW COMMISSION October 20, 2021

HDRC CASE NO:	2021-501
ADDRESS:	209 ALAMO PLAZA
LEGAL DESCRIPTION:	NCB 145 BLK LOT 5
ZONING:	D, H
CITY COUNCIL DIST.:	1
DISTRICT:	Alamo Plaza Historic District
APPLICANT:	David Hannan/Fisher Heck Architects
OWNER:	Suzy Pack
TYPE OF WORK:	Installation of a storefront system, exterior modifications, repair and maintenance, canopy installation
APPLICATION RECEIVED:	September 28, 2021
60-DAY REVIEW:	Not applicable due to City Council Emergency Orders
CASE MANAGER:	Edward Hall

REQUEST:

The applicant is requesting a Certificate of Appropriateness for approval to:

- 1. Perform rehabilitative scopes of work including window repair, fascia and soffit repair, storefront system repair on the east facade and masonry cleaning.
- 2. Install terra cotta on the existing pony walls on the east facade along with a key box.
- 3. Install a new, wood storefront system on the west façade to feature wood doors and a key box.
- 4. Install a new steel framed canopy on the west façade.
- 5. Relocate the existing roof hatch.

APPLICABLE CITATIONS:

Historic Design Guidelines, Chapter 2, Guidelines for Exterior Maintenance and Alterations

2. Materials: Masonry and Stucco

A. MAINTENANCE (PRESERVATION)

i. Paint—Avoid painting historically unpainted surfaces. Exceptions may be made for severely deteriorated material where other consolidation or stabilization methods are not appropriate. When painting is acceptable, utilize a water permeable paint to avoid trapping water within the masonry.

ii. Clear area—Keep the area where masonry or stucco meets the ground clear of water, moisture, and vegetation. *iii. Vegetation*—Avoid allowing ivy or other vegetation to grow on masonry or stucco walls, as it may loosen mortar and stucco and increase trapped moisture.

iv. Cleaning—Use the gentlest means possible to clean masonry and stucco when needed, as improper cleaning can damage the surface. Avoid the use of any abrasive, strong chemical, sandblasting, or high pressure cleaning method.

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

i. Patching—Repair masonry or stucco by patching or replacing it with in-kind materials whenever possible. Utilize similar materials that are compatible with the original in terms of composition, texture, application technique, color, and detail, when in-kind replacement is not possible. EIFS is not an appropriate patching or replacement material for stucco. *ii. Repointing*—The removal of old or deteriorated mortar should be done carefully by a professional to ensure that masonry units are not damaged in the process. Use mortar that matches the original in color, profile, and composition when repointing. Incompatible mortar can exceed the strength of historic masonry and results in deterioration. Ensure that the new joint matches the profile of the old joint when viewed in section. It is recommended that a test panel is prepared to ensure the mortar is the right strength and color.

iii. Removing paint—Take care when removing paint from masonry as the paint may be providing a protectant layer or hiding modifications to the building. Use the gentlest means possible, such as alkaline poultice cleaners and strippers, to remove paint from masonry. iv. Removing stucco—Remove stucco from masonry surfaces where it is historically inappropriate. Prepare a test panel to ensure that underlying masonry has not been irreversibly damaged before proceeding.

10. Commercial Facades

A. MAINTENANCE (PRESERVATION)

i. Character-defining features—Preserve character defining features such as cornice molding, upper-story windows, transoms, display windows, kickplates, entryways, tiled paving at entryways, parapet walls, bulkheads, and other features that contribute to the character of the building.

ii. Windows and doors—Use clear glass in display windows. See Guidelines for Architectural Features: Doors, Windows, and Screens for additional guidance.

iii. Missing features—Replace missing features in-kind based on evidence such as photographs, or match the style of the building and the period in which it was designed.

iv. Materials—Use in-kind materials or materials appropriate to the time period of the original commercial facade when making repairs.

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

i. New features—Do not introduce new facade elements that alter or destroy the historic building character, such as adding inappropriate materials; altering the size or shape of windows, doors, bulkheads, and transom openings; or altering the façade from commercial to residential. Alterations should not disrupt the rhythm of the commercial block. *ii. Historical commercial facades*—Return non-historic facades to the original design based on photographic evidence. Keep in mind that some non-original facades may have gained historic importance and should be retained. When evidence is not available, ensure the scale, design, materials, color, and texture is compatible with the historic building. Consider the features of the design holistically so as to not include elements from multiple buildings and styles.

11. Canopies and Awnings

A. MAINTENANCE (PRESERVATION)

i. Existing canopies and awnings—Preserve existing historic awnings and canopies through regular cleaning and periodic inspections of the support system to ensure they are secure.

B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

i. Replacement canopies and awnings—Replace canopies and awnings in-kind whenever possible.

ii. New canopies and awnings—Add canopies and awnings based on accurate evidence of the original, such as photographs. If no such evidence exists, the design of new canopies and awnings should be based on the architectural style of the building and be proportionate in shape and size to the scale of the building façade to which they will be attached. See UDC Section 35-609(j).

iii. Lighting—Do not internally illuminate awnings; however, lighting may be concealed in an awning to provide illumination to sidewalks or storefronts.

iv. Awning materials—Use fire-resistant canvas awnings that are striped or solid in a color that is appropriate to the period of the building.

v. Building features—Avoid obscuring building features such as arched transom windows with new canopies or awnings.

vi. Support structure—Support awnings with metal or wood frames, matching the historic support system whenever possible. Minimize damage to historic materials when anchoring the support system. For example, anchors should be inserted into mortar rather than brick. Ensure that the support structure is integrated into the structure of the building as to avoid stress on the structural stability of the façade.

FINDINGS:

- a. The applicant is requesting a Certificate of Appropriateness for approval to perform rehabilitative scopes of work, install a new storefront system, canopy and other exterior elements at 209 Alamo Plaza.
- b. The historic structure located at 209 S Alamo, in its two story form was constructed circa 1895. Structures on this site are found on the 1885 Sanborn Map; however, they do not exist in the height and footprint found on later Sanborn Maps.
- c. REHABILITATION The applicant has proposed to perform rehabilitative scopes of work including window repair, fascia and soffit repair, storefront system repair on the east facade and masonry cleaning. Staff finds the proposed scopes of work to be appropriate as the applicant has noted in-kind repair. Staff finds that all masonry cleaning should be done in a manner that does not damage brick. Additionally, the composite siding panel that

will be used on the under side of the soffit should feature a smooth finish. The existing storefront system and storefront system beam are not original.

- d. CEMENT BOARD PONY WALL The applicant has proposed to perform structural repairs to the existing pony walls, and in doing so, replace the existing finish of plaster with terra cotta tile. The Guidelines for Exterior Maintenance and Alterations 10.B.i., state that new features that alter or destroy the historic building character should not be introduced. Additionally, the Guidelines note that inappropriate materials should not be added. Staff finds the installation of terra cotta tile is not consistent with the Guidelines. Staff finds that the Guidelines should be followed regarding the historic façade, and that the scale, design, materials, color and texture of new materials should be compatible with those of the historic facade.
- e. STOREFRONT SYSTEM The applicant has proposed to install a new, wood storefront system on the west façade to feature wood doors and a key box. The existing storefront system has been obscured by non-original building materials. The Guidelines for Exterior Maintenance and Alterations 10.B.ii. note that non-historic facades should be returned to their original design based on photographic evidence. When evidence is not available, the scale, design, materials, color and texture of new materials should be compatible with those of the historic façade. Staff finds that the proposed new storefront system should feature a profile that is not consistent with those found historically on this building or the block.
- f. CANOPY The applicant has proposed to install a new steel framed canopy on the west façade. The Guidelines for Exterior Maintenance and Alterations 11.B.ii. notes that canopies should be added based on accurate evidence of the original, such as photographs. If no such evidence exists, the design of new canopies and awnings should be based on the architectural style of the building and be proportionate in shape and size to the scale of the building façade to which they will be attached. Generally, staff finds the installation of a canopy on the west façade to be appropriate; however, staff finds that the proposed height of the canopy is atypical with the historic placement of canopies, which are typically located above the storefront system and beneath transom windows. Additionally, staff finds that the proposed standing seam metal roof that is proposed for the canopy should feature smooth panels that are 18 to 21 inches in width, seams that are 1 to 2 inches in height, crimped ridges and a standard galvalume finish. Panels should not feature striations or corrugation. Lastly, staff finds that the proposed steel beam to by atypical with historic canopy design. Staff finds that the proposed canopy should feature a profile that is consistent with historic canopy details. Canopy rod anchors should not be installed through the face of historic masonry.
- g. ROOF HATCH RELOCATION The applicant has proposed to relocate that existing roof hatch. Generally, staff finds this to be appropriate provided that the profile of the roof and parapet walls remains unchanged.
- h. ARCHAEOLOGY The project shall comply with all federal, state, and local laws, rules, and regulations regarding archaeology, as applicable.

RECOMMENDATION:


- 1. Staff recommends approval of item #1, rehabilitative scope of work based on finding c with the following stipulations:
 - i. That all repair work be done in-kind.
 - ii. That the proposed composite panel on the underside of the soffit feature a smooth finish.
 - iii. That all masonry cleaning be done in a manner that does not damage the historic brick façade.
- 2. Staff does not recommend approval of item #2, the installation of terra cotta tile on the existing pony wall based on finding d. Staff recommends that the scale, design, materials, color and texture of new materials should be compatible with those of the historic facade. Additionally, staff recommends that the key box be relocated from a prominent location on the primary façade.
- 3. Staff does not recommend approval of item #3, the installation of a new storefront system as proposed. Staff recommends that a storefront system be installed that features a profile that is historically appropriate. Storefront openings, pony walls, mullions, and transom openings should be based on historic examples.
- 4. Staff recommends approval of item #4, the installation of a new canopy with the following stipulations:
 - i. That the canopy's height be reduced to be placed consistently with historic examples; commonly immediately between the storefront system and transom windows.
 - ii. That the proposed standing seam metal roof that is proposed for the canopy should feature smooth panels that are 18 to 21 inches in width, seams that are 1 to 2 inches in height, crimped ridges and a standard galvalume finish. Panels should not feature striations or corrugation.
 - iii. That the proposed canopy should feature a profile that is consistent with historic canopy details, The exposed steel beam should be modified or covered.

iv. That canopy rod anchors be installed in a manner that does not penetrate the face of existing masonry.

5. Staff recommends approval of item #5, roof hatch relocation with the stipulation that the existing roof and parapet wall profiles remain unchanged.

ARCHAEOLOGY – The project shall comply with all federal, state, and local laws, rules, and regulations regarding archaeology, as applicable.

City of San Antonio One Stop



October 14, 2021


CoSA Addresses

Community Service Centers

Pre-K Sites

BCAD Parcels

CoSA Parcels





September 28, 2021

City of San Antonio Office of Historic Preservation 1901 S. Alamo Street San Antonio, Texas 78204

Re: 209 Alamo Plaza San Antonio, TX 78205

To the HDRC Board:

The homeowner seeks approval to renovate the existing building located at 209 Alamo Plaza. The extent of the renovation encompasses the following scope of work:

Exterior Alterations – The plans propose the addition of a new awning to the rear end entrance of the building. The rear entrance will also see the addition of a new storefront system in the existing door openings that are currently walled off with a wood clad infill wall.

Roofing – There will be minimal work done on the roof. The work will consist of closing the existing roof hatch and creating a new opening for the roof hatch at a new location that will better work with the new layout of the interior. Work will be done in a way to preserve the structure of the roof as much as possible.

If there are any additional questions regarding the proposed scope of work, please let us know.

Sincerely,

David Hannan Jr., Principal Fisher Heck Architects 210-299-1500



EXISTING AERIAL MAP OF PROPERTY



EXISTING FRONTFACADE



EXISTING FRONT FAÇADE




EXISTING REAR FAÇADE



EXISTING REAR FAÇADE



EXISTING ROOF STRUCTURE



8/2021 9-42-26

	GENERAL NOTES	FISHER HECK A R C H I T E C T S 915 SOUTH ST MARY'S STREET SAN ANTONIO TEXAS FISHERHECK.COM 210-299-1500
PROPERTY LINE EXISTING	KEYNOTES	PRELIMINARY NOT FOR REGULATORY APPROVAL, PERMIT, OR CONSTRUCTION FISHER HECK, INC., ARCHITECTS MARK B. NAVARRO #25326 08/20/2021
		NUT NUT <tr< th=""></tr<>
		SHEET NO: A-100




<u>OWNER</u>


SUZY PACK 6951 WILLOW BEND ODESSA, TX 79762 PH: (432) 664-8104 EMAIL: suzybpack@gmail.com

ARCHITECT

FISHER HECK ARCHITECTS 915 S. ST. MARY'S STREET SAN ANTONIO, TX 78205 PH: (210) 299-1500 CONTACT: DAVID HANNAN JR EMAIL: dhannan@fisherheck.com


INTERIOR & EXTERIOR RENOVATION 209 ALAMO PLAZA





8/2021 9-42-26

	GENERAL NOTES	FISHER HECK A R C H I T E C T S 915 SOUTH ST MARY'S STREET SAN ANTONIO TEXAS FISHERHECK.COM 210-299-1500
PROPERTY LINE EXISTING	KEYNOTES	PRELIMINARY NOT FOR REGULATORY APPROVAL, PERMIT, OR CONSTRUCTION FISHER HECK, INC., ARCHITECTS MARK B. NAVARRO #25326 08/20/2021
		NUT NUT <tr< th=""></tr<>
		SHEET NO: A-100



8/2021 9-42-39 AM

3'-4"


38'-2"


			COMMERCIAL TENANT SPACE		
	11				
101		STORE 1 BELOW	00		
	A-401 7 207 UTILITY 206 UTILITY 207	6'-6" 16'-5"	BATHROOM 251 BEDROOM 250	13'-4" 1 1 1 1 1 1 1 1 1 1 1 1 1	

15'-4"

UTILITY 257

15'-9"





STRIP AND REPAIR EXISTING WOOD -WINDOWS, THEN PAINT. REFER TO GENERAL NOTES

EXISTING WALL MOUNTED SIGN


RECLAD FASCIA WITH SINGLE, 2X WOOD BEAM; PAINT TO MATCH STOREFONT. RECLAD UNDERSIDE OF SOFFIT WITH HARDIE PANEL, COLOR TO MATCH BEAM


UV PROTECTIVE FILM ON THE INTERIOR FACE OF THE GLASS

RECLAD & RESHEATH PONY WALLS W/ -CEMENT BOARD, DRAINAGE MAT, AND TERRA COTTA FILE. INSULATE WALL W/ ROCKWOOL INSULATION, THEN RECLAD INTERIOR WITH 5/8" TYP X GYP BOARD





	//////////////////////////////////	┟┯┿┲┿			
	//////////////////////////////////				
		┢┿┵┿			
		┠┰┶┰┶			
	//////////////////////////////////				
				┓╟╾┵┯╌┵┩╽┍╸╖╸╴╖╸	
STRIP AND REPAIR EXISTING	/////////				
WOOD WINDOWS, THEN PAINT.				╡╟╴┰└╴┰└╶╢╞══╫══╫══	╡╟┶╌┯┶╌┯
REFER TO GENERAL NOTES					
		╟┵┯┵╢╵		┘┟╌┼╌┼╢└╴╴║╴╴║	┛╟┯┶┯┷
	//////////				
		┠┯┷┯╢╽			
	///////////////////////////////////////			╡╟╴┯╌┵┯╌┷╢┝━━╫━━╫━━	╡╟┸┿┸┿
	/////////				
	//////////////////////////////////				
	//////////////////////////////////				
	//////////////////////////////////				
	//////////////////////////////////				
	/////////////////////////////////////				
	/////////////////////////////////////	╏╌╌└╌┌╟╴		<u>─┴┬┴╋┴┬┴┬┴┬┴</u>	-Y
	//////////				
STRIP AND REPAIR EXISTING			-		
WOOD WINDOWS, THEN PAINT.					
REFER TO GENERAL NOTES	//////////	┠┯┷┯╢			
	//////////				
	///////////////////////////////////////	$\left + - + + \right \right $			
	//////////////////////////////////				
	//////////////////////////////////				
		╏╧╌╌╧╄╧			╤╟┯╶┿╼╋┿
		╢╌╌╌└┟┲	┼╷┼╷┼╷┼╷┼	┱┶┲╪┲╧┲╋┲╧┲╧┲╧┲╧┲╧┲╧┲╧┲	┽┍┶┎┶╋┼╴
LOW PRESSURE WASH			НННН	HHHHHHHHHH	HHHH
			1		
EXISTING MASONRY SURFACE					
WITH PROSOCO SAFETY PEEL1					
	/////////	┠┶┯┷╢			
	//////////////////////////////////				
INSTALL OPAQUE MIRROR FILM					
ON INSIDE FACE OF GLASS	//////////////////////////////////				
WOOD STOREFRONT SYSTEM					
WOOD STOREFRONT SYSTEM					
WOOD STOREFRONT SYSTEM					
WOOD STOREFRONT SYSTEM					
WOOD STOREFRONT SYSTEM					
WOOD STOREFRONT SYSTEM					
WOOD STOREFRONT SYSTEM					
WOOD STOREFRONT SYSTEM					
WOOD STOREFRONT SYSTEM W/ DOUBLE-PANE, LAMINATED GLAZING; PAINT INSTALL OPAQUE MIRROR FILM			-		
WOOD STOREFRONT SYSTEM			-		
WOOD STOREFRONT SYSTEM W/ DOUBLE-PANE, LAMINATED GLAZING; PAINT INSTALL OPAQUE MIRROR FILM			-		
WOOD STOREFRONT SYSTEM W/ DOUBLE-PANE, LAMINATED GLAZING; PAINT INSTALL OPAQUE MIRROR FILM					
WOOD STOREFRONT SYSTEM W/ DOUBLE-PANE, LAMINATED GLAZING; PAINT INSTALL OPAQUE MIRROR FILM					
WOOD STOREFRONT SYSTEM W/ DOUBLE-PANE, LAMINATED GLAZING; PAINT INSTALL OPAQUE MIRROR FILM ON INSIDE FACE OF GLASS			-		
WOOD STOREFRONT SYSTEM W/ DOUBLE-PANE, LAMINATED GLAZING; PAINT INSTALL OPAQUE MIRROR FILM ON INSIDE FACE OF GLASS					
WOOD STOREFRONT SYSTEM W/ DOUBLE-PANE, LAMINATED GLAZING; PAINT INSTALL OPAQUE MIRROR FILM					
WOOD STOREFRONT SYSTEM W/ DOUBLE-PANE, LAMINATED GLAZING; PAINT INSTALL OPAQUE MIRROR FILM ON INSIDE FACE OF GLASS					






EQUAL





PROPOSED AWNING FOR REAR FACADE



STANDING SEAM METAL ROOF AWNING MATERIAL