#### HISTORIC AND DESIGN REVIEW COMMISSION April 06, 2022

HDRC CASE NO: 2022-183 **ADDRESS:** 138 KING WILLIAM **LEGAL DESCRIPTION:** NCB 737 BLK 2 LOT 9 **ZONING:** RM-4, H **CITY COUNCIL DIST.:** 1 **DISTRICT:** King William Historic District **APPLICANT:** NICHOLAS WHITELONIS/WHITELONIS NICHOLAS & AMANDA NICHOLAS WHITELONIS/WHITELONIS NICHOLAS & AMANDA **OWNER: TYPE OF WORK: Exterior** alterations **APPLICATION RECEIVED:** March 15, 2022 Not applicable due to City Council Emergency Orders **60-DAY REVIEW: CASE MANAGER:** Hannah Leighner **REQUEST:** 

The applicant is requesting a Certificate of Appropriateness for approval to remove the rear chimney.

#### **APPLICABLE CITATIONS:**

Historic Design Guidelines, Chapter 2, Exterior Maintenance and Alterations

#### 3. Materials: Roofs

#### A. MAINTENANCE (PRESERVATION)

i. Regular maintenance and cleaning—Avoid the build-up of accumulated dirt and retained moisture. This can lead to the growth of moss and other vegetation, which can lead to roof damage. Check roof surface for breaks or holes and flashing for open seams and repair as needed.

#### B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

i. Roof replacement—Consider roof replacement when more than 25-30 percent of the roof area is damaged or 25-30 percent of the roof tiles (slate, clay tile, or cement) or shingles are missing or damaged.

ii. Roof form—Preserve the original shape, line, pitch, and overhang of historic roofs when replacement is necessary. iii. Roof features—Preserve and repair distinctive roof features such as cornices, parapets, dormers, open eaves with exposed rafters and decorative or plain rafter tails, flared eaves or decorative purlins, and brackets with shaped ends. iv. Materials: sloped roofs—Replace roofing materials in-kind whenever possible when the roof must be replaced. Retain and re-use historic materials when large-scale replacement of roof materials other than asphalt shingles is required (e.g., slate or clay tiles). Salvaged materials should be re-used on roof forms that are most visible from the public right-of-way. Match new roofing materials to the original materials in terms of their scale, color, texture, profile, and style, or select materials consistent with the

building style, when in-kind replacement is not possible.

v. Materials: flat roofs—Allow use of contemporary roofing materials on flat or gently sloping roofs not visible from the public right-of-way.

vi. Materials: metal roofs—Use metal roofs on structures that historically had a metal roof or where a metal roof is appropriate for the style or construction period. Refer to Checklist for Metal Roofs on page 10 for desired metal roof specifications when considering a new metal roof. New metal roofs that adhere to these guidelines can be approved administratively as long as documentation can be provided

that shows that the home has historically had a metal roof.

vii. Roof vents—Maintain existing historic roof vents. When deteriorated beyond repair, replace roof vents in-kind or with one similar in design and material to those historically used when in-kind replacement is not possible.

#### 8. Architectural Features: Foundations

#### A. MAINTENANCE (PRESERVATION)

i. Details—Preserve the height, proportion, exposure, form, and details of a foundation such as decorative vents, grilles, and lattice work.

ii. Ventilation—Ensure foundations are vented to control moisture underneath the dwelling, preventing deterioration.

iii. Drainage—Ensure downspouts are directed away and soil is sloped away from the foundation to avoid moisture collection near the foundation.

iv. Repair—Inspect foundations regularly for sufficient drainage and ventilation, keeping it clear of vegetation. Also inspect for deteriorated materials such as limestone and repair accordingly. Refer to maintenance and alteration of applicable materials, for additional guidelines.

#### B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

i. Replacement features—Ensure that features such as decorative vents and grilles and lattice panels are replaced in-kind when deteriorated beyond repair. When in-kind replacement is not possible, use features matching in size, material, and design. Replacement skirting should consist of durable, proven materials, and should either match the existing siding or be applied to have minimal visual impact.

ii. Alternative materials—Cedar piers may be replaced with concrete piers if they are deteriorated beyond repair.

iii. Shoring—Provide proper support of the structure while the foundation is rebuilt or repaired.

iv. New utilities—Avoid placing new utility and mechanical connections through the foundation along the primary façade or where visible from the public right-of-way.


#### **FINDINGS:**

- a. The primary structure located at 138 King William is a two-story, residential structure with a wrap around porch and double height porch columns. The property is contributing to the King William Historic District.
- b. CHIMNEY REMOVAL The applicant has proposed to remove the existing chimney from the rear corner of the primary structure as part of foundation repairs. The Historic Design Guidelines 3.B.iii state that existing historic roof forms should be maintained. Staff finds the removal of the chimney to be inconsistent with the Guidelines. Staff finds that the exterior appearance of the chimney should not be impacted by foundation repair.

#### **RECOMMENDATION:**

Staff does not recommend approval based on finding b. The exterior appearance of the chimney should not be impacted by foundation repair.


### City of San Antonio One Stop



User drawn lines


		1:1,000	
0	0.0075	0.015	0.03 mi
$\vdash$	<u> </u>	, <u> ,   ,   </u> ,	<del></del>
0	0.0125	0.025	0.05 km

138 King William St - Google Maps




https://www.google.com/maps/place/138+King+William+St,+San+Antonio,+TX+78204/@29.4164103,-98.4909145,205m/data=!3m1!1e3!4m5!3m4!1s0x865c58af1f9c0111:0x842dd2d78f18c2fe!8m2!3d29.4164731!4d... 2/3


138 King William St - Google Maps



https://www.google.com/maps/place/138+King+William+St,+San+Antonio,+TX+78204/@29.4168169,-98.4918929,55a,35y,126.04h,55.53t/data=!3m1!1e3!4m5!3m4!1s0x865c58af1f9c0111:0x842dd2d78f18c2fe!8m2!... 2/3



https://www.google.com/maps/place/138+King+William+St,+San+Antonio,+TX+78204/@29.4161261,-98.4905414,42a,35y,312.94h,63.2t/data=!3m1!1e3!4m5!3m4!1s0x865c58af1f9c0111:0x842dd2d78f18c2fe!8m2!3... 2/3



https://www.google.com/maps/place/138+King+William+St,+San+Antonio,+TX+78204/@29.4159383,-98.4916506,60a,35y,39.22h,51.48t/data=!3m1!1e3!4m5!3m4!1s0x865c58af1f9c0111:0x842dd2d78f18c2fe!8m2!3... 2/3



https://www.google.com/maps/place/138+King+William+St,+San+Antonio,+TX+78204/@29.416264,-98.4905351,33a,50.2y,308.07h,60.72t/data=!3m1!1e3!4m5!3m4!1s0x865c58af1f9c0111:0x842dd2d78f18c2fe!8m2... 2/3

# Side Facing King William Street



# Side Facing Turner Street





# Side Facing Backyard



## Side Facing Adjacent Property







# Proposed Work

- Remove chimney
- Repair hole left in roof with matching shingles





### Area of Proposed Work

