



SURVEY NOTES:

1. BEARINGS, DISTANCES AND COORDINATES SHOWN FOR THIS SURVEY WERE DETERMINED BY GPS "RTK" OBSERVATIONS, NORTH AMERICAN DATUM OF 1983, TEXAS STATE PLANE COORDINATE SYSTEM, TEXAS SOUTH CENTRAL ZONE 4204, GRID.
2. SET 1/2" IRON RODS WITH CAP STAMPED "ALLIANCE LAND SURVEYORS RPLS 6500" AT ALL CORNERS UNLESS OTHERWISE NOTED.
3. CONTOURS SHOWN HEREON OBTAINED FROM SAN ANTONIO RIVER AUTHORITY'S LIDAR DATA.

SALVADOR FLORES, P.E. No. 82638
LICENSED PROFESSIONAL ENGINEER

I, CORY BLAKE SILVA, HEREBY CERTIFY THE THE ABOVE PLAT
CONFORMS TO THE MINIMUM STANDARDS SET FORTH BY THE
TEAS BOARD OF PROFESSIONAL LAND SURVEYING ACCORDING TO
AN ACTUAL SURVEY MADE ON THE GROUND BY:

CORY BLAKE SILVA
REGISTERED PROFESSIONAL LAND SURVEYOR
TEXAS REGISTRATION NO. 6500

[illegible]

DIRECTOR OF PUBLIC WORKS/ COUNTY ENGINEER, BEXAR COUNTY, TEXAS

