



**DEPARTMENT OF THE AIR FORCE
502D AIR BASE WING
JOINTBASE SAN ANTONIO**



21 Aug 2023

MEMORANDUM FOR CITY OF SAN ANTONIO

FROM: 502 ABW/CMI

JBSA Installation Encroachment Management
2080 Wilson Way
Fort Sam Houston, TX 78234

SUBJECT: Joint Base San Antonio review of Zoning Case Z-2-23-10700195 Old Sky Harbor and Spotted Deer Drive

1. Zoning Case Z-2-23-10700195 Old Sky Harbor and Spotted Deer Drive, has been reviewed by JBSA-LAK organizations. JBSA does not object with this request; however, there are additional comments for consideration in planning and development.
 - a. Subject property is within City of San Antonio Military Lighting Overlay District (MLOD), and will be required to comply with MLOD lighting standards at: https://library.municode.com/tx/san_antonio/codes/unified_development_code?nodeId=ARTII_IZO_DIV4OVDI_S35-339.04MILIOVDI, or most current City of San Antonio MLOD ordinance, related to military missions within 5-miles of a military installation.
 - b. Any construction plans, equipment (cranes), or towers (communication or water), will require an FAA aeronautical study.
 - c. To mitigate potential interference with existing JBSA operational systems, please coordinate with 502 CS Spectrum Manager prior to use of any Spectrum dependent systems (i.e.: two-way radio communications, or any type of wireless technologies) during construction. If applicable, coordination requested by facility user prior to installation/use of any Spectrum dependent commercial or manufacturing equipment.
 - d. The FAA recommends criteria of land-use practices in their Advisory Circular 150/5200-33C, Hazardous Wildlife Attractants on or Near Airports, which is applicable to properties within five miles of JBSA-Kelly Field. To reduce the exposure to aircraft-wildlife strikes, please use the link below to access this publication and use the information to help reduce wildlife-attractant features near airports. Unwavering consideration for this aviation safety hazard is vital.
https://www.faa.gov/airports/resources/advisory_circulars/index.cfm/go/document.current/documentnumber/150_5200-33.

- Point of contact for this action is Sean R. Greszler, AICP, 502 ABW/CMI. He can be reached at 210-808- 7549 or by email at sean.greszler.1@us.af.mil or through the 502d ABW Community Initiatives organization email box at 502ABW.ABW.Community_initiative@us.af.mil.

ANDERSON.JOHN.HENRY.1067670600
N.HENRY.1067670600
70600

Digitally signed by
ANDERSON.JOHN.HENRY.1067670600
DN:
cn=ANDERSON.JOHN.HENRY.1067670600, o=U.S. Government, ou=USAF,
email=unknown, c=US
Date: 2023-08-22T06:36:34-0500

JOHN H. ANDERSON, GS-14, USAF
JBSA Installation Encroachment Manager