# HISTORIC AND DESIGN REVIEW COMMISSION

# October 19, 2022

HDRC CASE NO: ADDRESS: LEGAL DESCRIPTION: ZONING: CITY COUNCIL DIST.: DISTRICT: APPLICANT: OWNER: TYPE OF WORK: APPLICATION RECEIVED: 60-DAY REVIEW:	2022-500 311 W ROSEWOOD AVE NCB 6532 BLK 12 LOT 17, 18, E 2 IN OF 16 & W 24.2 FT OF 19 R-5, H 1 Monte Vista Historic District DORIN REGUS/STONE OAK RENOVATIONS Roberto Varela/VARELA PROPERTIES LLC Window replacement, fenestration changes September 15, 2022 Not applicable due to City Council Emergency Orders
60-DAY REVIEW: CASE MANAGER:	•

# **REQUEST:**

The applicant is requesting a Certificate of Appropriateness for approval to:

- 1. Replace 27 windows on the primary structure.
- 2. Replace three sets of doors on the primary structure.
- 3. Add two new windows to the first floor of the primary structure.
- 4. Remove a small addition near the northeast corner of the rear accessory structure.
- 5. Infill two garage doors and two windows on the rear accessory structure.
- 6. Add eight windows to the rear accessory structure.
- 7. Remove a concrete path and steps between the rear accessory structure and the pool.

# **APPLICABLE CITATIONS:**

Historic Design Guidelines, Chapter 2, Exterior Maintenance and Alterations

6. Architectural Features: Doors, Windows, and Screens

A. MAINTENANCE (PRESERVATION)

- i. *Openings*—Preserve existing window and door openings. Avoid enlarging or diminishing to fit stock sizes or air conditioning units. Avoid filling in historic door or window openings. Avoid creating new primary entrances or window openings on the primary façade or where visible from the public right-of-way.
- ii. *Doors*—Preserve historic doors including hardware, fanlights, sidelights, pilasters, and entablatures.
- iii. *Windows*—Preserve historic windows. When glass is broken, the color and clarity of replacement glass should match the original historic glass.
- iv. Screens and shutters-Preserve historic window screens and shutters.
- v. *Storm windows*—Install full-view storm windows on the interior of windows for improved energy efficiency. Storm window may be installed on the exterior so long as the visual impact is minimal and original architectural details are not obscured.
- B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)
  - i. *Doors*—Replace doors, hardware, fanlight, sidelights, pilasters, and entablatures in-kind when possible and when deteriorated beyond repair. When in-kind replacement is not feasible, ensure features match the size, material, and profile of the historic element.
  - ii. *New entrances*—Ensure that new entrances, when necessary to comply with other regulations, are compatible in size, scale, shape, proportion, material, and massing with historic entrances.
- iii. *Glazed area*—Avoid installing interior floors or suspended ceilings that block the glazed area of historic windows.
- iv. *Window design*—Install new windows to match the historic or existing windows in terms of size, type, configuration, material, form, appearance, and detail when original windows are deteriorated beyond repair.
- v. *Muntins*—Use the exterior muntin pattern, profile, and size appropriate for the historic building when replacement windows are necessary. Do not use internal muntins sandwiched between layers of glass.

- vi. *Replacement glass*—Use clear glass when replacement glass is necessary. Do not use tinted glass, reflective glass, opaque glass, and other non-traditional glass types unless it was used historically. When established by the architectural style of the building, patterned, leaded, or colored glass can be used.
- vii. *Non-historic windows*—Replace non-historic incompatible windows with windows that are typical of the architectural style of the building.
- viii. Security bars—Install security bars only on the interior of windows and doors.
- ix. *Screens*—Utilize wood screen window frames matching in profile, size, and design of those historically found when the existing screens are deteriorated beyond repair. Ensure that the tint of replacement screens closely matches the original screens or those used historically.
- x. *Shutters*—Incorporate shutters only where they existed historically and where appropriate to the architectural style of the house. Shutters should match the height and width of the opening and be mounted to be operational or appear to be operational. Do not mount shutters directly onto any historic wall material.

# 9. Outbuildings, Including Garages

# A. MAINTENANCE (PRESERVATION)

- i. *Existing outbuildings*—Preserve existing historic outbuildings where they remain.
- ii. *Materials*—Repair outbuildings and their distinctive features in-kind. When new materials are needed, they should match existing materials in color, durability, and texture. Refer to maintenance and alteration of applicable materials above, for additional guidelines.

# B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

- i. *Garage doors*—Ensure that replacement garage doors are compatible with those found on historic garages in the district (e.g., wood paneled) as well as with the principal structure. When not visible from the public right-of-way, modern paneled garage doors may be acceptable.
- ii. *Replacement*—Replace historic outbuildings only if they are beyond repair. In-kind replacement is preferred; however, when it is not possible, ensure that they are reconstructed in the same location using similar scale, proportion, color, and materials as the original historic structure.
- iii. *Reconstruction*—Reconstruct outbuildings based on accurate evidence of the original, such as photographs. If no such evidence exists, the design should be based on the architectural style of the primary building and historic patterns in the district. Add permanent foundations to existing outbuildings where foundations did not historically exist only as a last resort.

# 12. Increasing Energy Efficiency

# A. MAINTENANCE (PRESERVATION)

i. *Historic elements*—Preserve elements of historic buildings that are energy efficient including awnings, porches, recessed entryways, overhangs, operable windows, and shutters.

# B. ALTERATIONS (REHABILITATION, RESTORATION, AND RECONSTRUCTION)

- i. *Weatherization*—Apply caulking and weather stripping to historic windows and doors to make them weather tight.
- ii. *Thermal performance*—Improve thermal performance of windows, fanlights, and sidelights by applying UV film or new glazing that reduces heat gain from sunlight on south and west facing facades only if the historic character can be maintained. Do not use reflective or tinted films.
- iii. *Windows* Restore original windows to working order. Install compatible and energy-efficient replacement windows when existing windows are deteriorated beyond repair. Replacement windows must match the appearance, materials, size, design, proportion, and profile of the original historic windows.
- iv. *Reopening*—Consider reopening an original opening that is presently blocked to add natural light and ventilation.
- v. *Insulation*—Insulate unfinished spaces with appropriate insulation ensuring proper ventilation, such as attics, basements, and crawl spaces.
- vi. *Shutters*—Reinstall functional shutters and awnings with elements similar in size and character where they existed historically.
- vii. Storm windows-Install full-view storm windows on the interior of windows for improved energy efficiency.
- viii. *Cool roofs*—Do not install white or —cool roofs when visible from the public right-of-way. White roofs are permitted on flat roofs and must be concealed with a parapet.
- ix. *Roof vents*—Add roof vents for ventilation of attic heat. Locate new roof vents on rear roof pitches, out of view of the public right-of-way.
- x. *Green Roofs*—Install green roofs when they are appropriate for historic commercial structures.

# Standard Specifications for Original Wood Window Replacement

- SCOPE OF REPAIR: When individual elements such as sills, muntins, rails, sashes, or glazing has deteriorated, every effort should be made to repair or reconstruct that individual element prior to consideration of wholesale replacement. For instance, applicant should replace individual sashes within the window system in lieu of full replacement with a new window unit.
- MISSING OR PREVIOUSLY-REPLACED WINDOWS: Where original windows are found to be missing or previously-replaced with a nonconforming window product by a previous owner, an alternative material to wood may be considered when the proposed replacement product is more consistent with the Historic Design Guidelines in terms of overall appearance. Such determination shall be made on a case-by-case basis by OHP and/or the HDRC. Whole window systems should match the size of historic windows on property unless otherwise approved.
- MATERIAL: If full window replacement is approved, the new windows must feature primed and painted wood exterior finish. Clad, composition, or non-wood options are not allowed unless explicitly approved by the commission.
- SASH: Meeting rails must be no taller than 1.25". Stiles must be no wider than 2.25". Top and bottom sashes must be equal in size unless otherwise approved.
- DEPTH: There should be a minimum of 2" in depth between the front face of the window trim and the front face of the top window sash. This must be accomplished by recessing the window sufficiently within the opening or with the installation of additional window trim to add thickness.
- TRIM: Original trim details and sills should be retained or repaired in kind. If approved, new window trim must feature traditional dimensions and architecturally appropriate casing and sloped sill detail. Window track components such as jamb liners must be painted to match the window trim or concealed by a wood window screen set within the opening.
- GLAZING: Replacement windows should feature clear glass. Low-e or reflective coatings are not recommended for replacements. The glazing should not feature faux divided lights with an interior grille. If approved to match a historic window configuration, the window should feature real exterior muntins.
- COLOR: Replacement windows should feature a painted finished. If a clad product is approved, white or metallic manufacturer's color is not allowed, and color selection must be presented to staff.
- INSTALLATION: Replacement windows should be supplied in a block frame and exclude nailing fins. Window opening sizes should not be altered to accommodate stock sizes prior to approval.
- FINAL APPROVAL: If the proposed window does not meet the aforementioned stipulations, then the applicant must submit updated window specifications to staff for review, prior to purchase and installation. For more assistance, the applicant may request the window supplier to coordinate with staff directly for verification.

# Standard Specifications for Windows in Additions and New Construction

- GENERAL: New windows on additions should relate to the windows of the primary historic structure in terms of materiality and overall appearance. Windows used in new construction should be similar in appearance to those commonly found within the district in terms of size, profile, and configuration. While no material is expressly prohibited by the Historic Design Guidelines, a high-quality wood or aluminum-clad wood window product often meets the Guidelines with the stipulations listed below. Whole window systems should match the size of historic windows on property unless otherwise approved.
- SIZE: Windows should feature traditional dimensions and proportions as found within the district.
- SASH: Meeting rails must be no taller than 1.25". Stiles must be no wider than 2.25". Top and bottom sashes must be equal in size unless otherwise approved.
- DEPTH: There should be a minimum of 2" in depth between the front face of the window trim and the front face of the top window sash.
- This must be accomplished by recessing the window sufficiently within the opening or with the installation of additional window trim to add thickness.
- TRIM: Window trim must feature traditional dimensions and architecturally appropriate casing and sloped sill detail. Window track components such as jamb liners must be painted to match the window trim or concealed by a wood window screen set within the opening.
- GLAZING: Windows should feature clear glass. Low-e or reflective coatings are not recommended for replacements. The glazing should not feature faux divided lights with an interior grille. If approved to match a historic window configuration, the window should feature real exterior muntins.

- COLOR: Wood windows should feature a painted finished. If a clad product is approved, white or metallic manufacturer's color is not allowed, and color selection must be presented to staff.
- INSTALLATION: Wood windows should be supplied in a block frame and exclude nailing fins. Window opening sizes should not be altered to accommodate stock sizes prior to approval.
- FINAL APPROVAL: If the proposed window does not meet the aforementioned stipulations, then the applicant must submit updated window specifications to staff for review, prior to purchase and installation. For more assistance, the applicant may request the window supplier to coordinate with staff directly for verification.

# FINDINGS:

- a. The property at 311 W Rosewood includes a two-story Spanish Eclectic residence with a rear one-story, twobay garage built c 1931. The house is clad in stucco with a barrel tile roof at the first floor and a flat roof with parapet on the second floor. Existing historic windows are one-over-one and wood sash, with modern windows found in both metal and vinyl at the northeast corner of the first floor and across much of the second floor. Sets of four thin ganged doors are found on the single-story west wing of the house; the south set of doors is historic, while the north set features modern wood replacement doors. The single-story rear garage is a split two-bay with attached living area. The northeast portion of the parcel is dominated by an in-ground pool. The property contributes to the Monte Vista historic district.
- b. ADMINISTRATIVE APPROVAL: The applicant requested approval to paint the exterior of the property. This scope of work is eligible for administrative review and approval and does not require HDRC review.
- c. WINDOW REPLACEMENT (PRIMARY): The applicant requests approval to replace 27 windows on the primary structure, including historic wood windows and modern vinyl- and metal-sash windows, with one-overone fiberglass windows. Historic Design Guidelines for Exterior Maintenance and Alterations 6.A.iii states that historic windows should be preserved, and 6.B.iv says that when original windows are deteriorated beyond repair, new windows should match the historic or existing windows in terms of size, type, configuration, material, form, appearance, and detail. Staff conducted a window inspection Friday, October 7, 2022, with the applicant present. On the first floor, staff determined that eight historic wood windows are in reparable condition and that four metal-sash windows and one vinyl window are eligible for replacement. Windows eligible for replacement are the three ganged windows numbered 10 and individual windows numbered 11 and 13 on the attached window schedule. On the second floor, staff determined three historic wood windows are in reparable condition, including the window at the stairwell landing. Nine modern windows are eligible for replacement, and two historic wood windows appear beyond repair. Second-floor windows eligible for replacement include those numbered 19-26 and 37 on the attached window schedule, plus an additional window not included on the floor plans on the west side of the northwest corner of the second floor. This window is currently closed from the inside, but the historic wood window is visible from the exterior. Though staff finds windows numbered 10 (three ganged windows), 11, 13, 19-26, and 37 on the attached window schedule and the west-facing window at the northwest corner of the second story are eligible for replacement, the fiberglass product proposed by the applicant does not conform to guidelines. A wood or aluminum-clad wood product conforms to guidelines as well as Standard Specifications for Original Wood Window Replacement. First-floor windows numbered 3, 4, 5 (three ganged windows), and 6-9 on the attached window schedule plus one window in the first-floor powder room should be retained and repaired. Second-floor windows numbered 15, 17, and 19 on the attached window schedule should also be retained and repaired. Staff has included in this case file a coded window schedule showing windows that should be retained in red and windows eligible for replacement in green.
- d. DOOR REPLACEMENT (PRIMARY): The applicant requests approval to replace two sets of wood doors on the west wing of the first floor and a pair of modern doors leading to a second-floor balcony on the south elevation. Historic Design Guidelines for Exterior Maintenance and Alterations 6.A.ii says historic doors should be preserved, including hardware, fanlights, sidelights, pilasters, and entablatures. Guideline 6.B.i says to replace doors, hardware, fanlight, sidelights, pilasters, and entablatures in-kind when possible and when deteriorated beyond repair, and when in-kind replacement is not feasible, ensure features match the size, material, and profile of the historic element. Staff conducted a window inspection Friday, October 7, 2022, with the applicant present; the inspection included doors proposed for replacement. Staff noted historic hinges and hardware on the north-facing west wing doors, but modern hardware on the south-facing west wing doors. The applicant proposes replacing the west wing doors with a pair of operable wood doors flanked by fixed 12-lite windows. Each set of doors includes four operable panels—i.e., each of the four panels opens away from the center of the configuration. Staff finds this condition should be replicated with replacement products. In-kind

replacement of the south-facing west wing doors conforms to guidelines, but staff finds the north-facing doors in operable condition. The pair of doors on the north side of the second floor are modern and are eligible for replacement. Staff finds the proposed pair of 15-lite wood doors conform to guidelines. Staff has included in this case file a coded window schedule showing doors that should be retained in red, namely the north-facing doors on the first-floor west wing, and doors eligible for replacement in green.

- e. FENESTRATION CHANGES (PRIMARY): The applicant requests approval to introduce two new windows on the first floor of the primary structure, numbered 12 and 14 on the attached window schedule. The windows are located on the rear (north) elevation and on the west elevation but screened by the west wing of the house. Staff finds the introduction of two new windows generally appropriate, but finds that the fiberglass window product proposed by the applicant does not conform to guidelines.
- f. PARTIAL DEMOLITION (GARAGE): The applicant requests approval to demolish a small addition at the northwest corner of the garage. The garage has been modified over time and no longer appears in its original footprint. Staff finds the removal of this addition appropriate.
- g. EXTERIOR MODIFICATIONS (GARAGE): The applicant requests to infill two garage doors and two windows, add eight windows and three sliding doors to the rear garage, and partially remove a concrete walkway between the garage and pool. Though Historic Design Guidelines for Exterior Maintenance and Alterations 9.A.i says existing historic outbuildings should be preserved where they remain, staff determined that the garage has undergone numerous modifications over the decades and is thus eligible for modification. Staff finds the applicant's requests generally appropriate.
- h. WINDOWS (GARAGE): The applicant proposes to replace introduce eight fiberglass windows to the garage. Standard Specifications for Windows in Additions and New Construction state that new windows should relate to the windows of the primary historic structure in terms of materiality and overall appearance. Whole window systems should match the size of historic windows on property unless otherwise approved. The applicant proposes a variety of sizes of windows for the garage: six 30"x60", one 36"x36", and one 12"x36" fixed-sash window. Staff finds this generally appropriate, but recommends a window with a more historic configuration in lieu of the fixed-sash window, such as a smaller one-over-one window. Staff also finds the fiberglass product proposed by the applicant does not conform to guidelines and finds a wood or aluminum-clad wood product would be more appropriate.
- i. DOORS (GARAGE): The applicant proposes to add three sets of fiberglass sliding doors on the south and east elevations of the garage. Staff finds a wood or aluminum-clad wood product would be more appropriate.

# **RECOMMENDATION:**

Staff recommends approval of item 1, window replacement on the primary structure, based on findings c through e, with the following stipulations:

- i. That first-floor windows numbered 3, 4, 5 (three ganged windows), and 6-9 on the attached window schedule plus one window in the first-floor powder room should be retained and repaired.
- ii. That second-floor windows numbered 15, 17, and 19 on the attached window schedule should be retained and repaired.
- iii. That the applicant propose a wood or aluminum-clad wood window product that conforms to guidelines and to Standard Specifications for Wood Window Replacement.
- iv. That the historic window pattern of the second story be retained, to include the window on the west side of the northwest corner that is currently closed from the inside.

Staff recommends approval of item 2, replacement of doors on the primary structure, based on finding d, with the following stipulation:

- i. That the north-facing doors on the west wing be retained and repaired.
- ii. That the south-facing doors on the west wing include four fully operable doors.

Staff recommends approval of item 3, addition of two windows to the first-floor of the primary structure, based on finding e, with the following stipulation:


i. That the applicant propose a wood or aluminum-clad wood window product that conforms to guidelines and to Standard Specifications for Wood Window Replacement.

Staff recommends approval of item 4, removal of a small addition near the northeast corner of the rear accessory structure, based on finding f.


Staff recommends approval of items 5 through 7 based on findings g through i, with the following stipulations:

i. That the applicant propose window and door products that are wood or aluminum-clad wood and otherwise conform to guidelines and Standard Specifications for Windows on Additions and New Construction.

# City of San Antonio One Stop



October 13, 2022



























# **OHP STAFF NOTES**

- H = Historic wood sash, to be retained
- H = Historic wood sash, but beyond repair
- V = Vinyl sash, eligible for replacement
- M = Metal sash, eligible for replacement
- W = Modern wood, eligible for replacement

1.2







# **OHP STAFF NOTES**

- H = Historic wood sash, to be retained
- H = Historic wood sash, but beyond repair
- V = Vinyl sash, eligible for replacement
- M = Metal sash, eligible for replacement
- W = Modern wood, eligible for replacement

1.3








HOME REMOPELING


1.4

THE ALL AND





# $\frac{\text{BACK ELEVATION - PROPOSED}}{1/4" = 1'-0"}$



# $\frac{\text{FRONT ELEVATION - PROPOSED}}{1/4" = 1'-0"}$

# PROPOSED 1ST FLOOR - DOOR & WINDOW SCHEDULE

#	QTY.	LOCATION	SIZE
$\langle 1 \rangle$	2	FRONT FORMAL DINING WINDOWS	25-1/4"W X 63-1/2"H SH
$\langle 2 \rangle$	1	FRONT FORMAL DINING WINDOW	37-1/4"W X 63-1/2"H SH
$\langle 3 \rangle$	2	FRONT FORMAL DINING SIDE WINDOW	37-1/4"X 63-1/2" SH
$\langle 4 \rangle$	1	FRONT DOOR – EXISTING REMAINING	NO CHANGE
$\left< 5 \right>$	1	DINING ROOM DOOR – EXISTING REMAINING	NO CHANGE
6	2	LIVING ROOM SIDE WINDOWS	31-1/4"W X 39-1/2"H SH
$\langle 7 \rangle$	1	LIVING ROOM FRONT DOOR	42"W X 98"H DOOR
$\langle 8 \rangle$	2	LIVING ROOM FRONT WINDOWS	23"W X 98"H FIXED WINDOW
$\langle 9 \rangle$	1	LIVING ROOM BACK DOOR	48-5/8"X 98" DOOR
(10)	2	LIVING ROOM BACK WINDOWS	25-7/16"W X 98"H FIXED WINDOW
$\langle 11 \rangle$	1	LAUNDRY WINDOW	35-1/2"W X 29-1/2"H SLIDER

# 1/4" = 1'-0"

$\langle 12 \rangle$	1	BATHROOM	24–1/2"W X 12"H SLIDER GLAZED
$\langle 13 \rangle$	3	DINING ROOM WINDOWS	35-1/2"W X 59-1/2"H SH
$\langle 14 \rangle$	2	DINING ROOM BACK WINDOWS	37-1/2"W X 59-1/2"H SH
(15)	2	KITCHEN WINDOWS	37-1/2"W X 37-1/2"H SH

# $\begin{array}{c} \hline \hline 16 \\ \hline 17 \\ \hline 18 \\ \hline 19 \\ \hline 20 \\ \hline 20 \\ \hline 21 \\ \hline 22 \\ \hline 22 \\ \hline 23 \\ \hline 24 \\ \end{array}$



SHEET

FRONT UPSTAIRS BATH WINDOW	25-1/4"W X 35-1/2"H SH
FRONT UPSTAIRS MST. BEDROOM DOOR	60-5/8"W X 82"H DOOR
FRONT UPSTAIRS MST. BEDROOM WINDOWS (RIGHT)	37-1/4"W X 63-1/2"H SH
FRONT UPSTAIRS MST. BEDROOM WINDOW (LEFT)	37-1/4"W X 51-1/2"H SH
STAIR WINDOW	31-1/4"W X 95-1/2"H SH
UPSTAIRS BATH WINDOW	29-1/2"W X 47-1/2"H SH
UPSTAIRS BEDROOM #2 WINDOW	12"W X 60-1/2"H FIXED
UPSTAIRS BEDROOM #2 WINDOWS	31-1/2"W X 61-1/2"H SH
UPSTAIRS BEDROOM #3 WINDOWS	35-1/2"W X 59-1/2"H SH

<u>NOTE:</u> FOR ADDITIONAL WINDOW SPECS, PLEASE SEE WINDOW MANUFACTURER.

WalCAD AS SHOWN Issue Date

PROPOSED ELEVATIONS

Reviewed By Bob King

Scale


Sheet Title

Designed By

Drawn By

WalCAD


09/28/2022






PROPOSED 1ST FLOOR – DOOR & WINDOW SCHEDULE				
#	QTY.	LOCATION	SIZE	
	2	FRONT FORMAL DINING WINDOWS	25-1/4"W X 63-1/2"H SH	
$\langle 2 \rangle$	1	FRONT FORMAL DINING WINDOW	37-1/4"W X 63-1/2"H SH	
$\overline{3}$	2	FRONT FORMAL DINING SIDE WINDOW	37-1/4" X 63-1/2" SH	
4	1	FRONT DOOR – EXISTING REMAINING	NO CHANGE	
$\left< 5 \right>$	1	DINING ROOM DOOR – EXISTING REMAINING	NO CHANGE	
6	2	LIVING ROOM SIDE WINDOWS	31-1/4"W X 39-1/2"H SH	
$\langle 7 \rangle$	1	LIVING ROOM FRONT DOOR	42"W X 98"H DOOR	
8	2	LIVING ROOM FRONT WINDOWS	23"W X 98"H FIXED WINDOW	
9	1	LIVING ROOM BACK DOOR	48-5/8" X 98" DOOR	
(10)	2	LIVING ROOM BACK WINDOWS	25-7/16"W X 98"H FIXED WINDOW	
$\langle 11 \rangle$	1	LAUNDRY WINDOW	35-1/2"W X 29-1/2"H SLIDER	
(12)	1	BATHROOM	24–1/2"W X 12"H SLIDER GLAZED	
(13)	3	DINING ROOM WINDOWS	35-1/2"W X 59-1/2"H SH	
$\langle 14 \rangle$	2	DINING ROOM BACK WINDOWS	37-1/2"W X 59-1/2"H SH	

(15)	2	KITCHEN WINDOWS
$\langle A \rangle$	1	FORMAL DINING ROOM
$\langle B \rangle$	1	BATHROOM DOOR
$\langle 0 \rangle$	1	LAUNDRY DOOR



AS SHOWN WalCAD Issue Date 07/29/2022





#	QTY.	LOCATION	SIZE
$\langle 16 \rangle$	1	FRONT UPSTAIRS BATH WINDOW	25-1/4"W X 35-1/2"H SH
(17)	1	FRONT UPSTAIRS MST. BEDROOM DOOR	60-5/8"W X 82"H DOOR
(18)	2	FRONT UPSTAIRS MST. BEDROOM WINDOWS (RIGHT)	37-1/4"W X 63-1/2"H SH
(19)	1	FRONT UPSTAIRS MST. BEDROOM WINDOW (LEFT)	37-1/4"W X 51-1/2"H SH
20>	1	STAIR WINDOW	31-1/4"W X 95-1/2"H SH
$\langle 21 \rangle$	1	UPSTAIRS BATH WINDOW	29-1/2"W X 47-1/2"H SH
22	1	UPSTAIRS BEDROOM #2 WINDOW	12"W X 60-1/2"H FIXED
23	3	UPSTAIRS BEDROOM #2 WINDOWS	31-1/2"W X 61-1/2"H SH
24	4	UPSTAIRS BEDROOM #3 WINDOWS	35-1/2"W X 59-1/2"H SH
	1	MST. BEDROOM CLOSET DBL. DOOR	48"W X 80"H WOOD DOOR
E	1	BATHROOM #1 DOOR	30"W X 80"H WOOD DOOR
F	1	MST. BEDROOM DOOR	36"W X 80"H WOOD DOOR
G	1	BEDROOM #2 DOOR	36"W X 80"H WOOD DOOR


$\langle H \rangle$	1	BEDRO
	1	BEDRO
	1	BEDRO
K	1	AC DO
	1	BATHR
$\langle L.1 \rangle$	1	LINEN

<u>NOTE:</u> FOR ADDITIONAL WINDOW SPECS, PLEASE SEE WINDOW MANUFACTURER.

WalCAD Drawn By Scale AS SHOWN WalCAD Issue Date

07/14/2022


SHEET



LIVING AREA

 $1 \quad CASITA FLOOR PLAN - EXISTING$ 








 $2 \frac{\text{CASITA FLOOR PLAN - PROPOSED}}{\frac{1}{4"} = 1'-0"}$ 

PROP	PROPOSED CASITA – DOOR & WINDOW SCHEDULE				
#	QTY.	LOCATION	SIZE		
25	5	BEDROOM #1 & LIVING ROOM WINDOWS	35-1/2"W X 59-1/2"H SH		
26	1	KITCHEN WINDOW	35-1/2"W X 35-1/2"H SH		
27	1	BATHROOM #1 WINDOW	35-1/2"W X 11-1/2"H FIXED GLAZED		
28	1	FRONT DOOR	36"W X 80"H WOOD DOOR		
29	3	BEDROOM #2, #3 & LIVING ROOM SLIDING DOOR	59-1/2"W X 79-1/2"H SLIDING DOOR		
$\langle M \rangle$	1	LIVING ROOM CLOSET DBL. DOOR	48"W X 80"H WOOD DOOR		
$\langle N \rangle$	3	BEDROOM #1, #2, #3 CLOSET DBL. DOOR	36"W X 80"H WOOD DOOR		
$\langle 0 \rangle$	3	BEDROOM #1, #2, #3 DOOR	32"W X 80"H WOOD DOOR		
$\langle P \rangle$	2	BATHROOM #1, #2 DOOR	30"W X 80"H WOOD DOOR		
$\langle Q \rangle$	1	WASHER/DRYER DOOR	32"W X 80"H WOOD DOOR		
$\langle R \rangle$	1	LINEN DOOR	24"W X 80"H WOOD DOOR		

<u>NOTE:</u> FOR ADDITIONAL WINDOW SPECS, PLEASE SEE WINDOW MANUFACTURER.





SHEET

Designed by	Incriewed by
WalCAD	Bob King
Drawn By	Scale
WalCAD	AS SHOWN
Issue Date	

07/14/2022







PROPOSED CASITA – DOOR & WINDOW SCHEDULE			
#	QTY.	LOCATION	SIZE
25	5	BEDROOM #1 & LIVING ROOM WINDOWS	35-1/2"W
(26)	1	KITCHEN WINDOW	35-1/2"W
27>	1	BATHROOM #1 WINDOW	35-1/2"W
28	1	FRONT DOOR	36"W X 80
29	3	BEDROOM #2, #3 & LIVING ROOM SLIDING DOOR	59-1/2"W

<u>NOTE:</u> FOR ADDITIONAL WINDOW SPECS, PLEASE SEE WINDOW MANUFACTURER.

W X 59-1/2"H SH W X 35-1/2"H SH W X 11-1/2"H FIXED GLAZED

80"H WOODEN DOOR

W X 79-1/2"H SLIDING DOOR

Sheet Title PROPOSED CASITA ELEVATIONS Designed By Reviewed By WalCAD Drawn By Bob King Scale AS SHOWN WalCAD

SHEET

Issue Date 09/28/2022



QUOTE EXPIRES Quote Not Certified

WINDOWS	BILL TO:	SHIP TO:

QUOTE #	QUOTE DATE	LOAD DATE	SHIP DATE	QUOTED BY
7087899	9/14/2022	Load Date Not Set	Quote Not Ordered	Bobby Garcia
JOB NAME		<b>CUSTOMER PO#</b>	<b>BUILDING/LOT #</b>	CONTACT


LineItem #	Description	Net Price	Extended
1-1 Qty: 1 Room Location: KITCHEN Note:	<ul> <li>Rough Opening: 108W x 60H</li> <li>3-0 5-0 Builders Series 1100 Single Hung (35.5 W x 59.5 H x 0 Leg), Equal Sash , Black/White, Nailing Fin</li> <li>Performance: PWG-M-3-01320-00001</li> <li>Glass: LE SC, Double Glazed, Tempered</li> <li>Screen: Half Screen, Charcoal Fiberglass, Shipped Separate</li> <li>Manufacturer Information: N/A</li> <li>Performance Rating: H-LC30, DP +30/-30; U-Factor = 0.35; SHGC = 0.23;</li> <li>VLT = 0.43; STC Rating = 27</li> <li>Frame Options: Nail Fin Setback-1 3/8"</li> <li>Clear Opening Calculations: 30.9375, 26.625, 5.72</li> <li>Mull 1 Type: Vertical FactoryMull</li> <li>Mull 2 Type: Vertical FactoryMull</li> </ul>	\$2,052.96	\$2,052.96
LineItem #	Description	Net Price	Extended

LineItem #	Description	Net Price	Extended
1-2 Otru 1	Unit 1 Screen: Half Screen, Charcoal Fiberglass, Shipped Separate	\$16.56	\$16.56
<b>Qty:</b> 1			

# **Room Location:**

# Note:

LineItem #	Description	Net Price	Extended
1-3	Unit 2 Screen: Half Screen, Charcoal Fiberglass, Shipped Separate	\$16.56	\$16.56
Qty: 1 Room Location:			





<b>QUOTE #</b>	QUOTE DATE	LOAD DATE	SHIP DATE	QUO	TED BY
7087899	9/14/2022	Load Date Not Set	Quote Not Ordered	Bobb	y Garcia
JOB N	NAME	<b>CUSTOMER PO#</b>	<b>BUILDING/LOT #</b>	CONTACT	
LineItem #	De	escription		Net Price	Extended
1-4	1-4 Unit 3 Screen: Half Screen, Charcoal Fiberglass, Shipped Separate		\$16.56	\$16.56	
<b>Qty:</b> 1					

# **Room Location:**

Note:

LineItem #	LineItem # Description		Extended
2-1 Qty: 1 Room Location: KITCHEN Note:	Rough Opening: 38W x 60H 3-2 5-0 Builders Series 1100 Single Hung (37.5 W x 59.5 H x 0 Leg), Equal Sash , Black/White, Nailing Fin Performance: PWG-M-3-00931-00001 Glass: LE SC, Double Glazed, Annealed Screen: Half Screen, Charcoal Fiberglass, Shipped Separate Manufacturer Information: N/A Performance Rating: H-LC30, DP +30/-30; U-Factor = 0.35; SHGC = 0.23; VLT = 0.44; STC Rating = 24 Frame Options: Nail Fin Setback-1 3/8" Clear Opening Calculations: 32.9375, 26.625, 6.09	\$497.10	\$497.10
LingIton #	Description	Not Drice	Futondod

LineItem #	Description	Net Price	Extended
2-2	Unit 1 Screen: Half Screen, Charcoal Fiberglass, Shipped Separate	\$18.40	\$18.40
<b>Qty:</b> 1		¢10.10	\$10.10
<b>Room Location:</b>			

LineItem #	Description	Net Price	Extended
3-1 Qty: 1 Room Location: LAUNDRY Note:	Rough Opening: 36W x 30H 3-0 2-6 Builders Series 1100 Horizontal Slider (35.5 W x 29.5 H x 0 Leg), Equal Sash , XO, Black/White Performance: PWG-M-4-00600-00001 Glass: LE SC, Double Glazed, Annealed Screen: Half Screen, Charcoal Fiberglass, Shipped Separate Manufacturer Information: N/A Performance Rating: R-PG35, DP+60/-60; U-Factor = 0.35; SHGC = 0.23; VLT = 0.44; STC Rating = 25 Frame Options: Nail Fin Setback-1 3/8" Clear Opening Calculations: 14.0625, 24.875, 2.43	\$402.03	\$402.03



<b>QUOTE #</b>	QUOTE DATE	LOAD DATE	SHIP DATE	QUO	TED BY
7087899	9/14/2022	Load Date Not Set	Quote Not Ordered	Bobb	y Garcia
JOB I	NAME	<b>CUSTOMER PO#</b>	<b>BUILDING/LOT #</b>	CONTACT	
LineItem #	De	escription		Net Price	Extended
3-2	Unit 1 Screen: Half S	Screen, Charcoal Fiberglass, Sł	nipped Separate	\$13.35	\$13.35
<b>Otv:</b> 1					

# Qty: 1

**Room Location:** 

Note:

LineItem #	Description	Net Price	Extended
4-1 Qty: 1 Room Location: KITCHEN Note:	Rough Opening: 20W x 48H 1-8 4-0 Builders Series 1100 Single Hung (19.5 W x 47.5 H x 0 Leg), Equal Sash , Black/White, Nailing Fin Performance: PWG-M-3-00931-00001 Glass: LE SC, Double Glazed, Annealed Screen: Half Screen, Charcoal Fiberglass, Shipped Separate Manufacturer Information: N/A Performance Rating: H-LC30, DP +30/-30; U-Factor = 0.35; SHGC = 0.23; VLT = 0.44; STC Rating = 24 Frame Options: Nail Fin Setback-1 3/8" Clear Opening Calculations: 14.9375, 20.625, 2.14	\$411.77	\$411.77

LineItem #	Description	Net Price	Extended
4-2	Unit 1 Screen: Half Screen, Charcoal Fiberglass, Shipped Separate	\$13.35	\$13.35
Qty: 1 Recom Location:			

**Room Location:** 

LineItem #	Description	Net Price	Extended
5-1 Qty: 1 Room Location: STAIRS Note:	Rough Opening: 32W x 96H 2-8 8-0 Builders Series 1100 Single Hung (31.5 W x 95.5 H x 0 Leg), 5-0 Sash , Black/White, Nailing Fin Performance: PWG-M-3-01320-00001 Glass: LE SC, Double Glazed, Tempered Hardware: Safety Vent Latch Screen: Half Screen, Charcoal Fiberglass, Shipped Separate Manufacturer Information: N/A Performance Rating: H-LC30, DP +30/-30; U-Factor = 0.35; SHGC = 0.23; VLT = 0.43; STC Rating = 27 Frame Options: Nail Fin Setback-1 3/8" Clear Opening Calculations: 26.9375, 26.625, 4.98	\$832.35	\$832.35



<b>QUOTE #</b>	QUOTE DATE	LOAD DATE	SHIP DATE	QUO	TED BY
7087899	9/14/2022	Load Date Not Set	Quote Not Ordered	Bobb	y Garcia
JOB NAME		<b>CUSTOMER PO#</b>	<b>BUILDING/LOT #</b>	CO	NTACT
LineItem #	De	escription		Net Price	Extended
5-2 Otv: 1	Unit 1 Screen: Half S	Screen, Charcoal Fiberglass, Sl	nipped Separate	\$14.71	\$14.71

# Qty: 1

**Room Location:** 

Note:

LineItem #	Description	Net Price	Extended
6-1 Qty: 1 Room Location: UPSTAIRS BATH Note:	Rough Opening: 30W x 48H 2-6 4-0 Builders Series 1100 Single Hung (29.5 W x 47.5 H x 0 Leg), Equal Sash , Black/White, Nailing Fin Performance: PWG-M-3-00931-00001 Glass: LE SC, Double Glazed, Annealed Screen: Half Screen, Charcoal Fiberglass, Shipped Separate Manufacturer Information: N/A Performance Rating: H-LC30, DP +30/-30; U-Factor = 0.35; SHGC = 0.23; VLT = 0.44; STC Rating = 24 Frame Options: Nail Fin Setback-1 3/8" Clear Opening Calculations: 24.9375, 20.625, 3.57	\$437.74	\$437.74
<b>T</b> • <b>T</b> ( ))		NT ( D ·	<b>F</b> ( <b>1 1</b>

LineItem #	Description	Net Price	Extended
6-2	Unit 1 Screen: Half Screen, Charcoal Fiberglass, Shipped Separate	\$13.35	\$13.35
<b>Qty:</b> 1		¢10.00	<i><b><i>ψ</i>10.00</b></i>
<b>Room Location:</b>			

LineItem #	Description	Net Price	Extended
7-1 Qty: 4 Room Location: UPSTAIRS BEDROO Note:	Rough Opening: 36W x 60H 3-0 5-0 Builders Series 1100 Single Hung (35.5 W x 59.5 H x 0 Leg), Equal Sash , Black/White, Nailing Fin Performance: PWG-M-3-00931-00001 Glass: LE SC, Double Glazed, Annealed Screen: Half Screen, Charcoal Fiberglass, Shipped Separate Manufacturer Information: N/A Performance Rating: H-LC30, DP +30/-30; U-Factor = 0.35; SHGC = 0.23; VLT = 0.44; STC Rating = 24 Frame Options: Nail Fin Setback-1 3/8" Clear Opening Calculations: 30.9375, 26.625, 5.72	\$470.48	\$1,881.92



<b>QUOTE #</b>	QUOTE DATE	LOAD DATE	SHIP DATE	QUO	TED BY
7087899	9/14/2022	Load Date Not Set	Quote Not Ordered	Bobb	oy Garcia
JOB M	NAME	<b>CUSTOMER PO#</b>	<b>BUILDING/LOT #</b>	CO	NTACT
LineItem #	De	escription		Net Price	Extended
7-2	Unit 1 Screen: Half S	Screen, Charcoal Fiberglass, Sł	nipped Separate	\$16.56	\$66.24
Otv: 4					

# Qty: 4

# **Room Location:**

Note:

LineItem #	Description	Net Price	Extended
8-1 Qty: 3 Room Location: UPSTAIRS BEDROO Note:	Rough Opening: 32W x 62H 2-8 5-2 Builders Series 1100 Single Hung (31.5 W x 61.5 H x 0 Leg), Equal Sash , Black/White, Nailing Fin Performance: PWG-M-3-00931-00001 Glass: LE SC, Double Glazed, Annealed Screen: Half Screen, Charcoal Fiberglass, Shipped Separate Manufacturer Information: N/A Performance Rating: H-LC30, DP +30/-30; U-Factor = 0.35; SHGC = 0.23; VLT = 0.44; STC Rating = 24 Frame Options: Nail Fin Setback-1 3/8" Clear Opening Calculations: 26.9375, 27.625, 5.17	\$468.90	\$1,406.70
LineItem #	Description	Not Price	Extended

	LineItem #	Description	Net Price	Extended
	8-2	Unit 1 Screen: Half Screen, Charcoal Fiberglass, Shipped Separate	\$15.21	\$45.63
Qty:	3			

**Room Location:** 

Note:

Total Unit Quantity: 28



QUOTE #	QUOTE DATE	LOAD DATE	SHIP DATE	QUOTED BY
7087899	9/14/2022	Load Date Not Set	Quote Not Ordered	Bobby Garcia
JOB NAME		<b>CUSTOMER PO#</b>	<b>BUILDING/LOT #</b>	CONTACT

PROJECT	QUOTE
311 West Rosewood	Stone Oak Renovations
	NOTES
Order:	
Delivery:	
Job Comment:	

8	
SUB-TOTAL:	\$8,157.28
LABOR:	\$0.00
FREIGHT:	\$0.00
SALES TAX:	\$652.58
TOTAL:	\$8,809.86

CUSTOMER SIGNATURE \_\_\_\_\_ DATE \_\_\_\_\_



# Stone Oak Renovation 311 West Rosewood

Quote #: Y121JK7

A Proposal for Window and Door Products prepared for: Job Site: 78132

Shipping Address: BFS-SAN ANTONIO 3620 FM 482 NEW BRAUNFELS, TX 78132-5015



BOBBY GARCIA BFS-SAN ANTONIO 3620 FM 482 NEW BRAUNFELS, TX 78132-5015 Phone: (830) 606-7020

Email: bobby.garcia@bldr.com

This report was generated on 9/15/2022 2:42:57 PM using the Marvin Order Management System, version 0003.16.01 (Current). Price in USD. Unit availability and price are subject to change. Dealer terms and conditions may apply.

Featuring products from:



# **UNIT SUMMARY**

The following is a schedule of the windows and doors for this project. For additional unit details, please see Line Item Quotes.

Additional charges, tax or Terms and Conditions may apply. Detail pricing is per unit.

NUME	BER OF LINES: 12	٦	TOTAL UNIT QTY: 19	EXT NET PRICE:	USD	47,367.18
LINE	MARK UNIT	PRODUCT LINE	ITEM	NET PRICE	QTY	EXTENDED NET PRICE
1	FRONT TRIPLE	Ultimate	Double Hung G2 CN 2028 RO 26 1/4" X 64"	1,035.54	3	3,106.62
3	FRONT RIGHT SIDE	Ultimate	Double Hung G2 CN 3228 RO 38 1/4" X 64"	1,174.55	2	2,349.10
5	LIVING ROOM	Ultimate	Double Hung G2 CN 2616 RO 32 1/4" X 40"	897.54	2	1,795.08
6	FRONT UPSTAIRS BEDROOM	Ultimate	Double Hung G2 CN 3228 RO 38 1/4" X 64"	1,174.55	2	2,349.10
7	FRONT UPSTAIRS BEDROOM	Ultimate	Double Hung G2 CN 3222 RO 38 1/4" X 52"	1,040.51	1	1,040.51
8	FRONT UPSTAIRS BATH	Ultimate	Double Hung G2 CN 2014 RO 26 1/4" X 36"	834.00	1	834.00
9	UPSTAIRS BEDROOM	Ultimate	Direct Glaze Rectangle RO 13" X 61"	995.83	1	995.83
10	UPSTAIRS FRONT BEDROOM	Ultimate	Inswing French Door G2 CN 5068 RO 61 5/8" X 82 1/2"	6,707.73	1	6,707.73
11	LIVING ROOM	Ultimate	Inswing French Door G2 RO 43" X 98 1/2"	8,350.92	1	8,350.92
12	LIVING ROOM	Ultimate	Inswing French Door G2 RO 24" X 98 1/2"	3,445.22	2	6,890.44
13	LIVING ROOM BACK	Ultimate	Inswing French Door G2 CN 2080 RO 26 7/16" X 98 1/2"	2,851.49	2	5,702.98
14	LIVING ROOM BACK	Ultimate	Inswing French Door G2 CN 4080 RO 49 5/8" X 98 1/2"	7,244.87	1	7,244.87


# LINE ITEM QUOTES

The following is a schedule of the windows and doors for this project. For additional unit details, please see Line Item Quotes. Additional charges, tax or Terms and Conditions may apply. Detail pricing is per unit.

Line #1 Mai	rk Unit: FRONT TRIPLE	Net Price:		1,035.54
Qty: 3		Ext. Net Price:	USD	3,106.62
MARVIN © MARVIN © MARVIN © Market Market As Viewed From CN 2028 FS 25 1/4" X 63 1/2" RO 26 1/4" X 64" Egress Information U-Factor: 0.29 Solar Heat Gain Coefficient Visible Light Transmittance Condensation Resistance: 5 CPD Number: MAR-N-425-1	White Interior Weather Strip Packag Black Exterior Weather Strip Package White Sash Lock White Top Sash Strike Plate Assemble Extruded Aluminum Screen Ebony Surround Bright View Mesh ***Screen/Combo Ship Loose 4 9/16" Jambs :: 0.2 Nailing Fin :: 0.46 ***Note: Unit Availability and Price is Su	rior ne Sash Interior ne Sash Interior	•••••	
ENERGY STAR: NC, SC, S				
				Seller:

Buyer: \_\_\_\_\_

Line #3	Mark Unit: FRONT RIGHT SIDE	Net Price:		1,174.55
Qty: 2		Ext. Net Price:	USD	2,349.10
MARVIN	Ebony Clad Exterior Painted Interior Finish - White - Pine Interi Ultimate Double Hung G2 CN 3228 Rough Opening 38 1/4" X 64" Glass Add For All Sash/Panels Top Sash Ebony Clad Sash Exterior Painted Interior Finish - White - Pine IG - 1 Lite Low E3 w/Argon Black Perimeter Bar Ogee Interior Glazing Profile Bottom Sash	or	• • • • • • • • •	
	<b>o o</b>	e Sash Interior		



As Viewed From The Exterior

CN 3228 FS 37 1/4" X 63 1/2" RO 38 1/4" X 64" Egress Information Width: 33 21/32" Height: 26 11/16" Net Clear Opening: 6.24 SqFt Performance Information U-Factor: 0.29 Solar Heat Gain Coefficient: 0.2 Visible Light Transmittance: 0.46 Condensation Resistance: 56 CPD Number: MAR-N-425-17158-00001 ENERGY STAR: NC, SC, S

Low E3 w/Argon Black Perimeter Bar Ogee Interior Glazing Profile White Interior Weather Strip Package Black Exterior Weather Strip Package White Sash Lock White Top Sash Strike Plate Assembly Color Extruded Aluminum Screen Ebony Surround **Bright View Mesh** \*\*\*Screen/Combo Ship Loose 4 9/16" Jambs Nailing Fin \*\*\*Note: Unit Availability and Price is Subject to Change

Initials required

Seller: \_\_\_\_\_

Buyer: \_\_\_\_\_

Line #5	Mark Unit: LIVING ROOM		Net Price:		897.54
Qty: 2			Ext. Net Price:	USD	1,795.08
	Ultimate Double Hung G2 CN 2616 Rough Opening 32 1/4" X 40' Glass Add For All Sash/Pane Top Sash Ebony Clad Sash Exterio Painted Interior Finish - IG - 1 Lite Low E3 w/Argon Black Perimeter Bar Ogee Interior Glazing I Bottom Sash Ebony Clad Sash Exterio Painted Interior Finish - IG - 1 Lite Low E3 w/Argon Black Perimeter Bar Ogee Interior Glazing I White Interior Weather St Black Exterior Weather St White Sash Lock White Top Sash Strike Pla Aluminum Screen Ebony Surround Bright View Mesh ***Screen/Combo Ship Loo 4 9/16" Jambs Nailing Fin ***Note: Unit Availability an	Is or White - Pine Profile or White - Pine Profile trip Package rip Package te Assembly (	or Sash Interior Sash Interior	•••••	

OMS Ver. 0003.16.01 (Current)

Buyer: \_\_\_\_

Line #6 N	1ark Unit: FRONT UF	STAIRS BEDROOM	Net Price:		1,174.55
Qty: 2			Ext. Net Price:	USD	2,349.10
Qty: 2 MARVIN ⊚		Ebony Clad Exterior Painted Interior Finish - White - Pine Int Ultimate Double Hung G2 CN 3228 Rough Opening 38 1/4" X 64" Glass Add For All Sash/Panels Top Sash Ebony Clad Sash Exterior Painted Interior Finish - White - P IG - 1 Lite Low E3 w/Argon Black Perimeter Bar Ogee Interior Glazing Profile Bottom Sash Ebony Clad Sash Exterior	erior	••••••••••	
		IG - 1 Lite Low E3 w/Argon Black Perimeter Bar Ogee Interior Glazing Profile			
As Viewed Fro CN 3228 FS 37 1/4" X 63 1/2" RO 38 1/4" X 64" Egress Information Width: 33 21/32" Heig Net Clear Opening: 6.24 Performance Informatio U-Factor: 0.29 Solar Heat Gain Coefficie Visible Light Transmittar	ht: 26 11/16" SqFt on ent: 0.2 nce: 0.46	Ogee Interior Glazing Profile White Interior Weather Strip Packa Black Exterior Weather Strip Packa White Sash Lock White Top Sash Strike Plate Assemt Extruded Aluminum Screen Ebony Surround Bright View Mesh ***Screen/Combo Ship Loose 4 9/16" Jambs Nailing Fin ***Note: Unit Availability and Price is S	ge bly Color		
Condensation Resistance CPD Number: MAR-N-42 ENERGY STAR: NC, SC, S					Initials required
					Seller:

Buyer:

Line #7 Mark Unit: FRONT UPSTAIRS BEDROOM Net Price: 1,040.51 Ext. Net Price: USD 1,040.51 Qty: 1 Ebony Clad Exterior MARVIN 🥹 CN 3222 Rough Opening 38 1/4" X 52" Glass Add For All Sash/Panels 30.78 Top Sash Ebony Clad Sash Exterior Painted Interior Finish - White - Pine Sash Interior IG - 1 Lite Low E3 w/Argon Black Perimeter Bar Ogee Interior Glazing Profile **Bottom Sash** Ebony Clad Sash Exterior Painted Interior Finish - White - Pine Sash Interior IG - 1 Lite Low E3 w/Argon Black Perimeter Bar **Ogee Interior Glazing Profile** As Viewed From The Exterior

CN 3222
en olle
<b>FS</b> 37 1/4" X 51 1/2"
<b>RO</b> 38 1/4" X 52"
Egress Information
Width: 33 21/32" Height: 20 11/16"
Net Clear Opening: 4.84 SqFt
Performance Information
U-Factor: 0.29
Solar Heat Gain Coefficient: 0.2
Visible Light Transmittance: 0.46
Condensation Resistance: 56
CPD Number: MAR-N-425-17158-00001
ENERGY STAR: NC, SC, S

White Interior Weather Strip Package Black Exterior Weather Strip Package White Sash Lock White Top Sash Strike Plate Assembly Color Aluminum Screen Ebony Surround Bright View Mesh \*\*\*Screen/Combo Ship Loose 4 9/16" Jambs Nailing Fin \*\*\*Note: Unit Availability and Price is Subject to Change

Initials required


Seller: \_\_\_\_\_

Buyer: \_\_\_\_\_

Line #8       Mark Unit: FRONT UPSTAIRS BATH       Net Price:       834.00         Cty: 1       Ext. Net Price:       USD       834.00         MARVIN ©       East Net Price:       USD       834.00         MARVIN ©       Image: State						
Image: Characterized status       Ebony Clad Exterior         Painted Interior Finish - White - Pine Interior       14.92         Ultimate Double Hung G2       669.19         CN 2014       Rough Opening 26 1/4" X 36"         Glass Add For All Sash/Panels       14.89         Pointed Interior Finish - White - Pine Sash Interior       16 - 1 Lite         Low K3 W/Argon       Black Perimeter Bar         Ogee Interior Glazing Profile       Bottom Sash         Ebony Clad Sash Exterior       Painted Interior Finish - White - Pine Sash Interior         IG - 1 Lite       Low K3 W/Argon         Black Perimeter Bar       Ogee Interior Glazing Profile         Bottom Sash       Ebony Clad Sash Exterior         Painted Interior Finish - White - Pine Sash Interior       IG - 1 Lite         Low K3 W/Argon       Black Perimeter Bar         Ogee Interior Glazing Profile       White Sash Lock         White Sash Lock       White Sash Strike Plate Assembly Color         Aluminum Screen       Ebony Surround         Bright View Mesh       ***Screen/Combo Ship Loose         Yisibul Light Transmittance: 0.46       Condensation Resistance: 56         Cord Number: MAR-M-25: 517158-00001       Exercen/Combo Ship Loose         Yisibul Light Transmittance: 0.45       Nailing Fin         **	Line #8	Mark Unit: FRONT UP	STAIRS BATH	Net Price:		834.00
MARVIN ©Painted Interior Finish - White - Pine Interior	Qty: 1			Ext. Net Price:	USD	834.00
	MARVIN © MARVIN © MARVIN © Market Market Market As Viewed I CN 2014 FS 25 1/4" X 35 1/2" RO 26 1/4" X 36" Egress Information Width: 21 21/32" H Net Clear Opening: 1 Performance Inform U-Factor: 0.29 Solar Heat Gain Coef Visible Light Transmi Condensation Resist CPD Number: MAR-f	From The Exterior Height: 12 11/16" 91 SqFt mation ficient: 0.2 ttance: 0.46 ance: 56 N-425-17158-00001	Painted Interior Finish - White - Pine Interi Ultimate Double Hung G2 CN 2014 Rough Opening 26 1/4" X 36" Glass Add For All Sash/Panels Top Sash Ebony Clad Sash Exterior Painted Interior Finish - White - Pine IG - 1 Lite Low E3 w/Argon Black Perimeter Bar Ogee Interior Glazing Profile Bottom Sash Ebony Clad Sash Exterior Painted Interior Finish - White - Pine IG - 1 Lite Low E3 w/Argon Black Perimeter Bar Ogee Interior Glazing Profile White Interior Weather Strip Package Black Exterior Weather Strip Package Black Exterior Weather Strip Package White Sash Lock White Top Sash Strike Plate Assembly Aluminum Screen Ebony Surround Bright View Mesh ***Screen/Combo Ship Loose 4 9/16" Jambs Nailing Fin	or e Sash Interior e Sash Interior Color	•••••	

Buyer: \_\_\_\_\_

Line #9	Mark Unit: UPSTAIRS BEDROOM	Net Price:		995.83
Qty: 1		Ext. Net Price:	USD	995.83
MARVIN 🍥	Ebony Clad Exterior Painted Interior Finish - White - Pine Inter Ultimate Direct Glaze Rectangle Rough Opening 13" X 61"			



Performance Information U-Factor: 0.3 Solar Heat Gain Coefficient: 0.22 Visible Light Transmittance: 0.5 Condensation Resistance: 55 CPD Number: MAR-N-419-08060-00001 ENERGY STAR: NC, SC, S

Line #10 Qty: 1	Mark Unit: UPSTAIRS FRONT BEDROOM	Net Price: Ext. Net Price:	USD	6,707.73 6,707.73
MARVIN (2)	Right Panel Ebony Clad Sash Exterior Painted Interior Finish - White - Pin	e Sash Interior nish - White - Pine Int		83.40
As Viewed Fr CN 5068 FS 60 5/8" X 82" RO 61 5/8" X 82 1/2" Egress Information Width: 53 3/16" Heig Net Clear Opening: 28 Performance Informa U-Factor: 0.3 Solar Heat Gain Coeffi Visible Light Transmitt CPD Number: MAR-N- ENERGY STAR: N, NC, 5	9.94 SqFt     Ogee Interior Glazing Profile       ition     Traditional Lever(s)       Multi-Point Lock on Active Panel     Oil Rubbed Bronze PVD Active Exteri       icient: 0.14     Non-Keyed       tance: 0.32     Oil Rubbed Bronze PVD Active Interior       476-02993-00001     Multi-Point Lock on Inactive Panel	nish - White - Pine Int or Handle Set on Active Pan or Handle Set on Active Pane prior Handle Set on Inactive P rior Handle Set on Inactive P	el el Panel Panel	
OMS Ver. 0003.16.0	01 (Current) Processed on: 9/15/2022 2:42:5	57 PM		Page 7 of 13

# Thru Jamb Installation w/ Nailing Fin \*\*\*Note: Unit Availability and Price is Subject to Change

Initials required

```
Seller: _____
```

```
Buyer: _____
```

1:			Net Dula	I	0.250.03
Line #11	Mark Unit: LIVING RO	JM	Net Price:		8,350.92
Qty: 1			Ext. Net Price:	USD	8,350.92
MARVIN (©)	From The Exterior eight: 94 11/32" 22.64 SqFt mation fficient: 0.14 ittance: 0.32 N-476-02980-00005	Ebony Clad Exterior Painted Interior Finish - White - Pine Interior Ultimate Inswing French Door G2 4 9/16" Frame Size 42" X Call Number 80 Rough Opening 43" X 98 1/2" Glass Add For All Sash/Panels Left Panel OM 19 3/4" X CN 80 Ebony Clad Sash Exterior Painted Interior Finish - White - Pine IG Tempered Low E3 w/Argon Black Perimeter and Spacer Bar 7/8" SDL - With Spacer Bar - Black, Rectangular - Special Cut 2W6H Ebony Clad Ext - Painted Interior Fin Ogee Interior Glazing Profile Right Panel OM 19 3/4" X CN 80 Ebony Clad Sash Exterior Painted Interior Finish - White - Pine IG Tempered Low E3 w/Argon Black Perimeter and Spacer Bar 7/8" SDL - With Spacer Bar - Black, Rectangular - Special Cut 2W6H Ebony Clad Sash Exterior Painted Interior Finish - White - Pine IG Tempered Low E3 w/Argon Black Perimeter and Spacer Bar 7/8" SDL - With Spacer Bar - Black, Rectangular - Special Cut 2W6H Ebony Clad Ext - Painted Interior Fir Ogee Interior Glazing Profile Traditional Lever(s) Multi-Point Lock on Active Panel Oil Rubbed Bronze PVD Active Exteri Oil Rubbed Bronze PVD Active Exteri Oil Rubbed Bronze PVD Active Exteri Oil Rubbed Bronze PVD Inactive Interior Keyed Alike - Keyed Alike Group 1, . Multi-Point Lock on Inactive Panel Oil Rubbed Bronze PVD Inactive Exteri Oil Rubbed Bronze PVD Inactive Interior Keyed Alike - Keyed Alike Group 1, . Multi-Point Lock on Inactive Panel Oil Rubbed Bronze PVD Inactive Exteri Oil Rubbed Bronze PVD Inactive Exteri Oil Rubbed Bronze PVD Inactive Interior Keyed Alike - Keyed Alike Group 1, . Multi-Point Lock on Inactive Panel Oil Rubbed Bronze PVD Inactive Interior Keyed Alike - Keyed Alike - Ke	or - XX Left Hand - XX Left Hand e Sash Interior hish - White - Pine Int e Sash Interior hish - White - Pine Int or Handle Set on Active Pane or Handle Set on Active Pane or Handle Set on Inactive Pane Panel-	el Keyed el Keyed el Panel	

Seller: \_\_\_\_\_

Buyer: \_\_\_\_\_

Line #12	Mark Unit: LIVING ROOM	Net Price:		3,445.22
Qty: 2		Ext. Net Price:	USD	6,890.44




#### OMS Ver. 0003.16.01 (Current) Product availability and pricing subject to change.

	Ultimate Inswing French Door G2 4 9/16" - 0 Frame Size 23" X Call Number 80 Rough Opening 24" X 98 1/2" Glass Add For All Sash/Panels OM 20 5/8" X CN 80 Ebony Clad Sash Exterior Painted Interior Finish - White - Pine Sash Interior IG Tempered Low E3 w/Argon Black Perimeter and Spacer Bar	
Stat Stat As Viewed From The Exterior FS 23" X 98" RO 24" X 98 1/2"	7/8" SDL - With Spacer Bar - Black Rectangular - Special Cut 2W6H Ebony Clad Ext - Painted Interior Finish - White - Pine Int Ogee Interior Glazing Profile Bronze Ultrex Sill Black Weather Strip 4 9/16" Jambs Thru Jamb Installation w/ Nailing Fin ***Note: Unit Availability and Price is Subject to Change	643.37
Egress Information No Egress Information available.	li Li	nitials required
Performance Information		Seller:
Solar Heat Gain Coefficient: 0.14 Visible Light Transmittance: 0.32 CPD Number: MAR-N-476-02980-00005 ENERGY STAR: N, NC, SC, S		Buyer:

Line #13 N	Mark Unit: LIVING ROOM BACK	Net Price:		2,851.49
Qty: 2		Ext. Net Price:	USD	5,702.98
MARVIN ()	Ebony Clad Exterior Painted Interior Finish - White - Pine Inter Ultimate Inswing French Door G2 4 9/16 CN 2080 Rough Opening 26 7/16" X 98 1/2" Glass Add For All Sash/Panels Ebony Clad Sash Exterior Painted Interior Finish - White - P IG Tempered Low E3 w/Argon Black Perimeter and Spacer Bar 7/8" SDL - With Spacer Bar - Black Rectangular - Standard Cut 2W6H Ebony Clad Ext - Painted Interior I Ogee Interior Glazing Profile Bronze Ultrex Sill Black Weather Strip 4 9/16" Jambs Thru Jamb Installation w/ Nailing Fin ***Note: Unit Availability and Price is S	erior " - 0 ine Sash Interior 		
CN 2080 FS 25 7/16" X 98" RO 26 7/16" X 98 1/2" Egress Information No Egress Information a Performance Informati U-Factor: 0.3 Solar Heat Gain Coeffici Visible Light Transmitta CPD Number: MAR-N-4 ENERGY STAR: N, NC, SO	ion ient: 0.14 ince: 0.32 76-02980-00005			Initials required Seller:

Line #14	Mark Unit: LIVING ROOM BACK	Net Price:		7,244.87
Qty: 1		Ext. Net Price:	USD	7,244.87

Ebony Clad Exterior



U-Factor: 0.3 Solar Heat Gain Coefficient: 0.14 Visible Light Transmittance: 0.32 CPD Number: MAR-N-476-02980-00005 ENERGY STAR: N, NC, SC, S

Painted Interior Finish - White - Pine Interior       512.31         Ultimate Inswing French Door G2 4 9/16" - XX Right Hand       4,886.84
CN 4080
Rough Opening 49 5/8" X 98 1/2"
Glass Add For All Sash/Panels 80.42
Left Panel
Ebony Clad Sash Exterior
Painted Interior Finish - White - Pine Sash Interior
IG
Tempered Low E3 w/Argon
Black Perimeter and Spacer Bar
7/8" SDL - With Spacer Bar - Black
Rectangular - Standard Cut 2W6H
Ebony Clad Ext - Painted Interior Finish - White - Pine Int
Ogee Interior Glazing Profile
Right Panel
Ebony Clad Sash Exterior
Painted Interior Finish - White - Pine Sash Interior
Tempered Low E3 w/Argon
Black Perimeter and Spacer Bar
7/8" SDL - With Spacer Bar - Black476.57
Rectangular - Standard Cut 2W6H
Ebony Clad Ext - Painted Interior Finish - White - Pine Int
Ogee Interior Glazing Profile
Traditional Lever(s)
Multi-Point Lock on Active Panel
Oil Rubbed Bronze PVD Active Exterior Handle Set on Active Panel Keyed
Oil Rubbed Bronze PVD Active Interior Handle Set on Active Panel
Keyed Alike - Keyed Alike Group 1
Multi-Point Lock on Inactive Panel
Oil Rubbed Bronze PVD Inactive Exterior Handle Set on Inactive Panel
Oil Rubbed Bronze PVD Inactive Interior Handle Set on Inactive Panel
Dark Bronze Adjustable Hinges 3 Per Panel77.44
Bronze Ultrex Sill
Black Weather Strip
4 9/16" Jambs
Thru Jamb Installation w/ Nailing Fin
***Note: Unit Availability and Price is Subject to Change
Initials required

Seller: \_\_\_\_\_

Buyer: \_\_\_\_\_

Project Subtotal Net Price: USD	47,367.18
8.250% Sales Tax: USD	3,907.79
Project Total Net Price: USD	51,274.97

## **TERMS AND CONDITIONS**

#### PRODUCT AND PERFORMANCE INFORMATION

NFRC energy ratings and values may vary depending on the exact configuration of glass thickness used on the unit. This data may change over time due to ongoing product changes or updated test results or requirements.

The National Fenestration Rating Council (NFRC) has developed and operates a uniform national rating system for the energy performance of fenestration products, including windows and doors. For additional information regarding this rating system, see www.nfrc.org.

NFRC energy values and ratings may change over time due to ongoing product changes, updated test results or requirements.

#### **PURCHASE APPROVAL/SIGN OFF**

### Project Subtotal Net Price: USD 47,367.18 8.250% Sales Tax: USD 3,907.79

# Project Total Net Price: USD 51,274.97

I have reviewed all line item quotes in detail and agree that the product specifications and pricing are accurate, and I approve the project for order. I acknowledge that additional charges, tax or Terms and Conditions may apply.

Seller: \_\_\_\_\_

Buyer: \_\_\_\_\_



QUOTE EXPIRES

9/14/2022

WINDO	WS	BILL TO:	SHIP TO:	
OUOTE #	OUOTE DATE	LOAD DATE	SHIP DATE	OUOTED BY

QUOTE #	QUOTE DATE	LOAD DATE	SHIP DATE	QUOTED BY
7087912	9/14/2022	Load Date Not Set	Quote Not Ordered	Bobby Garcia
JOB NAME		<b>CUSTOMER PO#</b>	<b>BUILDING/LOT #</b>	CONTACT

LineItem #	Description	Net Price	Extended
1-1 Qty: 5 Room Location: CASITA Note:	Rough Opening: 36W x 60H 3-0 5-0 Builders Series 1100 Single Hung (35.5 W x 59.5 H x 0 Leg), Equal Sash , Black/White, Nailing Fin Performance: PWG-M-3-00931-00001 Glass: LE SC, Double Glazed, Annealed Screen: Half Screen, Charcoal Fiberglass, Shipped Separate Manufacturer Information: N/A Performance Rating: H-LC30, DP +30/-30; U-Factor = 0.35; SHGC = 0.23; VLT = 0.44; STC Rating = 24 Frame Options: Nail Fin Setback-1 3/8" Clear Opening Calculations: 30.9375, 26.625, 5.72	\$470.48	\$2,352.40

LineItem #	Description	Net Price	Extended
1-2	Unit 1 Screen: Half Screen, Charcoal Fiberglass, Shipped Separate	\$16.56	\$82.80
Qty: 5			

**Room Location:** 

Note:

LineItem #	Description	Net Price	Extended
2-1 Qty: 1 Room Location: CASITA Note:	Rough Opening: 36W x 36H 3-0 3-0 Builders Series 1100 Single Hung (35.5 W x 35.5 H x 0 Leg), Equal Sash , Black/White, Nailing Fin Performance: PWG-M-3-00931-00001 Glass: LE SC, Double Glazed, Annealed Screen: Half Screen, Charcoal Fiberglass, Shipped Separate Manufacturer Information: N/A Performance Rating: H-LC30, DP +30/-30; U-Factor = 0.35; SHGC = 0.23; VLT = 0.44; STC Rating = 24 Frame Options: Nail Fin Setback-1 3/8" Clear Opening Calculations: 30.9375, 14.625, 3.14	\$429.85	\$429.85



QUOTE #	QUOTE DATE	LOAD DATE	SHIP DATE	QUO	TED BY
7087912	9/14/2022	Load Date Not Set	Quote Not Ordered	Bobb	y Garcia
JOB I	NAME	CUSTOMER PO#	<b>BUILDING/LOT #</b>	CO	NTACT
LineItem #	De	escription		Net Price	Extended
	Unit 1 Screen: Half Screen, Charcoal Fiberglass, Shipped Separate				
2-2	Unit I Screen: Half S	Screen, Charcoal Fiberglass, S	hipped Separate	\$13.35	\$13.35

**Room Location:** 

Note:

LineItem #	Description	Net Price	Extended
3-1 Qty: 1 Room Location: CASITA SHOWER Note:	Rough Opening: 36W x 12H 3-0 1-0 Builders Series 1100 Rectangle (35.5 W x 11.5 H x 0 Leg), Black/White, Nailing Fin Performance: PWG-M-1-00960-00001 Glass: LE SC, Double Glazed, Annealed Manufacturer Information: N/A Performance Rating: F-R50, DP +50/-50; U-Factor = 0.33; SHGC = 0.24; VLT = 0.47 Frame Options: Nail Fin Setback-1 3/8"	\$184.58	\$184.58

LineItem #	Description	Net Price	Extended
4-1 Qty: 1 Room Location: CASITA Note:	Rough Opening: 60W x 80H 5-0 6-8 Builders Series 1100 Two Panel (59.5 W x 79.5 H x 0 Leg), OX, Black/White Performance: PWG-M-60-00819-00001 Glass: LE SC, Double Glazed, Tempered Hardware: Handle: Standard, Keyed Alike Screen: Screen, Charcoal Fiberglass, Shipped Separate Manufacturer Information: N/A Performance Rating: SGD-R35, DP +35/-40; U-Factor = 0.33; SHGC = 0.23; VLT = 0.43; STC Rating = 27 Frame Options: Nail Fin Setback-1 1/2", Frame Depth-4 13/16"	\$918.00	\$918.00

LineItem #	Description	Net Price	Extended
4-2	Unit 1 Screen: Screen, Charcoal Fiberglass, Shipped Separate	\$73.68	\$73.68
<b>Qty:</b> 1		<i><b>4</b>7<b>6</b>100</i>	470100

**Room Location:** 

Note:



QUOTE #	QUOTE DATE	LOAD DATE	SHIP DATE	QUO	TED BY
7087912	9/14/2022	Load Date Not Set	Quote Not Ordered	Bobb	y Garcia
JOB N	NAME	CUSTOMER PO#	<b>BUILDING/LOT #</b>	CO	NTACT
LineItem #	De	escription		Net Price	Extended
5-1 Qty: 1 Room Location: CASITA Note:	5-0 6-8 Builders Seri Black/White Performance: PWG-I Glass: LE SC, Doubl Hardware: Handle: S Screen: Screen, Char Manufacturer Inform Performance Rating: 0.23; VLT = 0.43; ST	Rough Opening: 60W x 80H 5-0 6-8 Builders Series 1100 Two Panel (59.5 W x 79.5 H x 0 Leg), OX,		\$918.00	\$918.00
LineItem #	De	escription		Net Price	Extended
5-2	Unit 1 Screen: Screen	n, Charcoal Fiberglass, Shippe	d Separate	\$73.68	\$73.68

**Qty:** 1

**Room Location:** 

Note:

LineItem #	Description	Net Price	Extended
6-1	Rough Opening: 60W x 80H 5-0 6-8 Builders Series 1100 Two Panel (59.5 W x 79.5 H x 0 Leg), XO,	\$918.00	\$918.00
Qty: 1 Room Location:	Black/White Performance: PWG-M-60-00819-00001		
CASITA Note:	Glass: LE SC, Double Glazed, Tempered Hardware: Handle: Standard, Keyed Alike		
	Screen: Screen, Charcoal Fiberglass, Shipped Separate	982 0	
	Manufacturer Information: N/A Performance Rating: SGD-R35, DP +35/-40; U-Factor = 0.33; SHGC = 0.23; VLT = 0.43; STC Rating = 27	1	
	Frame Options: Nail Fin Setback-1 1/2", Frame Depth-4 13/16"		<u>_</u>
LineItem #	Description	Net Price	Extended

Lineitein $\pi$	Description		Extended	
6-2	Unit 1 Screen: Screen, Charcoal Fiberglass, Shipped Separate	\$73.68	\$73.68	
<b>Qty:</b> 1				

**Room Location:** 

Note:

Total Unit Quantity: 19



QUOTE #	QUOTE DATE	LOAD DATE	SHIP DATE	QUOTED BY
7087912	9/14/2022	Load Date Not Set	Quote Not Ordered	Bobby Garcia
JOB NAME		CUSTOMER PO#	<b>BUILDING/LOT #</b>	CONTACT

PROJECT	QUOTE
311 Rosewood CASITA	Stone Oak Renovations
N	OTES
Order:	
Delivery:	
Job Comment:	

_	_
SUB-TOTAL:	\$6,038.02
LABOR:	\$0.00
FREIGHT:	\$0.00
SALES TAX:	\$230.27
TOTAL:	\$6,268.29

CUSTOMER SIGNATURE \_\_\_\_\_ DATE \_\_\_\_\_

















Ding .





0











































































ALL
A SALAN AND A SALAN
A REALIZED BELIEVES
A MARINA STATES
et a state of the
HANNELS AND AND S
1
AND THE PROPERTY
THE STATE OF ALL
APPROXIMATE TAIL
ABRARDI - TAN
NA CONTRACTOR
ATEN OV MUSE REPORT
BLEER AND AND
THE ALL
The state
10-20-218
al aller
the Bar Mit
Bad A Martin





















1		
	Construction and the second of	
	The Rest of the State of the St	
	Carthe State We will be with the state of th	5
		F
	The state of the s	
	The second state of the se	







